

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-73

5a. Indicate Type of Lease
State ☒ Fee ☐
5. State Oil & Gas Lease No.
A-1212

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL ☒ GAS WELL ☐ OTHER ☐
Name of Operator
AMOCO PRODUCTION COMPANY
Address of Operator
P.O. BOX 68 HOBBS, NEW MEXICO 88240
Location of well
UNIT LETTER **J** **2310** FEET FROM THE **South** LINE AND **1650** FEET FROM
THE **East** LINE, SECTION **4** TOWNSHIP **19-S** RANGE **38-E** NMPM.

7. Unit Agreement Name
8. Farm or Lease Name
South Hobbs (GSA) Unit
9. Well No.
44
10. Field and Pool, or Wildcat
Hobbs GSA
11. County
LEA

15. Elevation (Show whether DF, RT, GR, etc.)
3611' DF

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐
OTHER **Squeeze Zone I and Repair Csg** ☒

PLUG AND ABANDON ☐
CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOBS ☐
OTHER ☐
ALTERING CASING ☐
PLUG AND ABANDONMENT ☐

7. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

MISW and POH w/ prod. equipment. Plug well back from current PBTD of 4220' to 4085' w/ 20/40 sand. Tag SN and cap w/ 5' calseal. New PBTD should be 4080'. RIH w/ cmt ret. and SA 3850'. Pump 50 sx class 'C' neat followed by 50 sx class C w/ add. Reverse out excess cmt and WDC. POH. Perforate at 2740' w/ 43SPF using a 3 1/8" csg gun and 90° phasing. Pump down the 4 1/2" csg to establish circulation through the 6 5/8" and 10 3/4" csg. Calc cement volume. RIH w/ cmt ret and SA 2650'. Pump 1000 sx (or vol. calculated) class 'C' neat and circulate through 6 5/8" and 10 3/4" annulus. Close annular valve and obtain squeeze pressure of 1000 psi. Reverse out excess cmt.

0+5 NMOC-D-H, 1-JTB, 1-FJN, 1-NLG

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

CHECKED **Ch. L. Jeter** TITLE **Administrative Analyst** DATE **12 May 1985**

PROVED BY **ORIGINAL SIGNED BY DEPT. SECRETARY** TITLE **DEPT. SECRETARY** DATE **MAY 14 1985**
CONDITIONS OF APPROVAL, IF ANY:

Perf at 500' w/ 4 JSF using 3 1/8" csg gun and 90° phasing.
Establish circ through 10 3/4" - 16" annulus, RHT w/ pkr and SA
250'. Pump 450 sx class 'C' neat, Disp w/ 3.9 bbl water,
WOC. POH w/ pkr and tag, RHT w/ bit and DO to 600'.
prs test to 1000 psi. DO to 2000' and prs tst to 1000 psi.
DO to 4010' and prs tst to 1000 psi. DO to 4070' and prs
tst to 1000 psi. CO to 4200'. RHT w/ prod equip and
MOSL.