

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
P. O. BOX 2048
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-7-73

1a. Indicate Type of Lease	
State ☐	For ☒
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE APPLICATION FOR PERMIT - 1 (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	7. Unit Agreement Name
2. Name of Operator Amoco Production Company	8. Name or Lease Name South Hobbs (GSA) Unit
3. Address of Operator P. O. Box 68, Hobbs, NM 88240	9. Well No. 56
4. Location of Well UNIT LETTER <u>P</u> <u>660</u> FEET FROM THE <u>South</u> <u>660</u> FEET FROM THE <u>East</u> LINE, SECTION <u>4</u> TOWNSHIP <u>19-S</u> RANGE <u>38-E</u> NMPM.	10. Field and Pool, or Wildcat Hobbs GSA
15. Elevation (Show whether DF, RT, GR, etc.) 3610' DF	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☒	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
FULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOBS ☐	OTHER ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Pulled tbg, drill collars, & bit. Ran tbg & pkr w/pkr set at 2013'. Lowered pkr to 2400'. Raised pkr to 2369' & spotted w/250 gal 15% acid. Set pkr at 2000'. Ran tbg & retrievable bridge plug set at 3860'. Pulled tbg & ran cmt bond log. Pulled pkr & tbg. Perforated 2450'w/4 JSPF. Ran pkr & tbg w/pkr set at 2401'. Reset pkr at 2280'. Pulled pkr & tbg. Ran 8-5/8" cmt retainer to 2243'. Pumped 13 bbl. fresh water & 125 sx 50-50 Class H w/caseal & 35 sx Class H. Flushed w/4 bbl. Pulled tbg. Ran bit, drill collars, & tbg. Drilled retainer at 2243' & drilled cmt 2246'-2455'. Ran bit to 2515'. Pulled tbg, drill collars & bit. Ran pkr & set at 2400'. Bled pressure off and pulled pkr. Pulled tbg. Ran tbg. Tagged fill at 3242'. Cleaned out fill & sn to 3499'. Released retrievable bridge plug. Pulled tbg & retrievable bridge plug. Ran bit, drill collars, & tbg. Tagged cast iron bridge plug at 3900'. Drilled out bridge plug. Lowered bit to 4171'. Tagged fill & drilled to 4187'. Raised bit to 3900'. Lowered bit & tagged at 4178'. Drilled to 4191' & pulled tbg & tools. Ran 7" magnet & 7-5/8" Globe basket. Tagged at 4191'. Ran 8" Mill and raise Globe Basket to 3900'. Lower Mill to 4191'. Ran Magnet & tbg to 4191'. Circulated w/work magnet & pulled magnet full of junk. Ran magnet & tbg. to 4192'. Preparing to run 7-5/8" flat bottom mill.

0+4-NMOCD, H 1-Hou 1-Susp 1-CLF

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Cathy L. Forman TITLE Assist. Admin. Analyst DATE 9-29-81

APPROVED BY [Signature] TITLE [Signature] DATE 9-29-81
CONDITIONS OF APPROVAL, IF ANY: DISCLOSED