

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.
7. Unit Agreement Name
8. Farm or Lease Name State A-5
9. Well No. 2
10. Field and Pool, or Wildcat Hobbs G-SA
12. County Lea

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT - " (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator Continental Oil Company
3. Address of Operator P. O. Box 460, Hobbs, NM 88240
4. Location of Well UNIT LETTER <u>0</u> , <u>990'</u> FEET FROM THE <u>South</u> LINE AND <u>1650</u> FEET FROM THE <u>East</u> LINE, SECTION <u>5</u> TOWNSHIP <u>19-S</u> RANGE <u>38E</u> NMPM.
15. Elevation (Show whether DF, RT, GR, etc.) <u>3617' df</u>

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPER. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <u>loosing hole</u> <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1109.

Drl'd. cmt 4086-4100'. Drl'd BP @ 4100' & lost corc. Ran Cmt. bond long. Perf w/1 JSPF @ 4030, 32, 36, 38, 42, 44, 4124, 32, 36, 50, 53, 58, and 4160'. Set pkr at 4145' & trtd. Perfs w/750 gals 28% acid. Set BP at 4145' and Pkr at 4100' and trtd perfs 4124-4136' w/750 gals 28% acid. Set RBP at 4055' and trtd. perfs 4020-4044' w/1500 gals 28% acid. Swbd. large volume of gas. Spotted Sd on BP w/bailer to 4060'. Set pkr at 3856' and pmpd. in 137 sks Class "C" cmt and sq. perfs 3956-4044'. Located hole in 5 1/2" csg at 985'. Sq. w/180 sks Class "C" cmt. Sq. 80 sks in form. Drl'd out firm cmt. to 985. C/O to 990' and tested sq. w/1000 psi. Hold O.K. Drl'd stringers to 1027' & stopped. Began rec. metal cuttings. Ran Imp. block. Indicated bit teeth cutting into 5 1/2" csg. C/O red bed and cmt. to 1028'. Milled 4027-4029. Tagged fill at 1024' and C/O to 1039'. Red bed heaving. Unable to C.O. Well permanently abandoned, pending P&A. Replacement well is presently being drilled.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>M. E. Peasley</u>	TITLE <u>Admin. Supervisor</u>	DATE <u>7-30-73</u>
APPROVED BY <u>Joe D. Ramey</u> Dist. 4, Supv.	TITLE _____	DATE <u>AUG 8 1973</u>