

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

OIL CONSERVATION DIVISION

DISTRICT I
P.O. Box 1980, Hobbs NM 88241-1980

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

2040 Pacheco St.
Santa Fe, NM 87505

WELL API NO.	30-025-07625
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	
7. Lease Name or Unit Agreement Name	SOUTH HOBBS (GB/SA) UNIT
8. Well No.	12
9. Pool name or Wildcat	HOBBS GB/SA

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	2. Name of Operator ALTURA ENERGY, LTD.	3. Address of Operator P.O. BOX 4294 HOUSTON, TEXAS 79210-4294
4. Well Location Unit Letter D : 330 Feet From The NORTH Line and 330 Feet From The WEST Line Section 5 Township 19-S Range 38-E NMPM LEA NM County	10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3629' DF	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 1) MIRU PLUGGING UNIT.
- 2) RIH W/TBG, TAG TOC @ 3565'.
- 3) CIRC HOLE W/MLF.
- 4) SPOT 30 SXS CLASS "C" CMT @ 3565'-3465'.
- 5) SPOT 30 SXS CMT @ 2590'-2490'.
- 6) SPOT 30 SXS CMT @ 1775'-1675'.
- 7) SPOT 30 SXS CMT @ 235'-135'.
- 8) SPOT 10 SXS CMT 30'-SURFACE.
- 9) CUT OFF WELL HEAD, INSTALL DRY HOLE MARKER.

NOTIFY NM OCD 24 HRS PRIOR TO RIGGING UP

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Roger Massey TITLE SENIOR P & A SUPERVISOR DATE 12-22-97
TYPE OR PRINT NAME ROGER MASSEY TELEPHONE NO. (915) 530-0907

(This space for State Use)

ORIGINAL SIGNED BY CHRIS WILLIAMS
DISTRICT I SUPERVISOR

DEC 23 1997

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY: _____