DISTRIBUTION SANTA FE NEW MEXICO OIL CONSERVATION COMMISSION	Form C-103 Supersedes Old C-102 and C-103 Effective 1-1-65
U.S.G.S. LAND OFFICE	5a. Indicate Type of Lease State X Fee.
OPERATOR	5. State Oil & Gas Lease No. A-166
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)	7. Unit Agreement Name
OIL X GAS OTHER-	
2. Name of Operator	8. Farm or Lease Name
Atlantic Richfield Company 3. Address of Operator	O. O. Bradley 9. Well No.
P. O. Box 1710, Hobbs, New Mexico 88240	3
4. Location of Well	10. Field and Pool, or Wildcat
UNIT LETTER B 330 FEET FROM THE NORTH LINE AND 1650 FEET FROM	Bowers Seven Rivers
THE East LINE, SECTION 6 TOWNSHIP 198 RANGE 38E NMPM.	
15. Elevation (Show whether DF, RT, GR, etc.)	12. County
3637' DF	Lea
Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON COMMENCE DRILLING OPNS. PULL OR ALTER CASING CHANGE PLANS CASING TEST AND CEMENT JQB. OTHER	ALTERING CASING PLUG AND ABANDONMENT X
OTHER	
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.	
1. On 10/17/75 rigged up, pulled rods & tbg, installed BOP. 2. WIH w/5% CIBP on WL, set @ 3125'. RIH w/2-3/8" tbg & spotted 10 sx Cl C cmt, 71' on top of BP.	
3. Spotted heavy gelled mud between all cmt plugs. 4. Spotted 12 sx Cl C cmt in 5½" OD csg (100' plug) across top of salt @ 1600'. 5. Spotted 10 sx Cl C cmt @ surface.	
6. Installed regulation dry hole marker, cleaned & leveled location. Your office to be notified when location is ready for final inspection.	
to the desired the information above is true and complete to the best of my knowledge and belief.	

Dist. Drlg. Supv.

DATE 11/5/75

CONDITIONS OF APPROVAL, IF ANY: