STALE OF NEW MEXICO	5 1C+1T			-	
ENERGY AND MINEPALS DEPART		L CONSERVATION DIVISIO			Form 0-103
DISTRIBUTION		P. O. BOX 2088			
JANTAFE	SAN	SANTA FE, NEW MEXICO 37501			Revised 10
FILE	_			٢	Su. Indicate Type of Leise
U.S.G.S.					State Foo
LAND OFFICE					5. state Off & Gas Lease No.
OPERATO.					
SUN	DRY NOTICES AND	REPORTS ON WEL	S DIFFERENT RESERVOIA		
USE "APPLICATION FOR FERMIT -" FORM C-1011 FOR SUCH PROPRACE.					7. Unit Agreement Nume
	Ir	njection			
weit weit	OTHER-				d. Farm or Lease Name
2. Hame of Operator					South Hobbs (GSA) U
Amoco Production Company					19, well No.
1. Address of Operator					115
P. O. Box 68, Hobbs, New Mexico 88240					
A Location of Well			·		10. Field and Pool, or #Edect
I	2310	South	330	FET FROM	Hobbs GSA
UNIT LETTER		W THE CI			UUUUUUUUUU
East	6	19-S	38-E		
THE LUSC LINE, S	ECTION	TOWNSHIP	_ RANGE	NMPU.	SUMMANNAN S
Milling (Milling) (15. Elevation (Show whether DF, RT, GR, etc.)					112. County ALLI
	())))))) 13. E.OM	3631' KB			Lea Cilili
To. Che	ck Appropriate Bo:	x To Indicate Natur	e of Motice, Repo	rt or Ot	her Data
	F INTENTION TO:	1	SUBS	SEQUEN	T REPORT OF:
	B1 1	IG AND ABANDON REA	AEDIAL WORK	X	ALTERING CASING
PERFORM PEMEOIAL WORK	,		IMENCE DRILLING OPHS.	$\overline{\Box}$	PEUG AND ABANODHME
TEMPORANILT ASAHOON	-		ING TEST AND CEMENT JO	, T	
PULL OR ALTER CASING	Сна			ب -	
			OTHER		

17. Descritie Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, WOIK SEE RULE 1103.

Moved in service unit 12-28-82. Pulled tubing and packer. Spotted 900# of sand. Tagged sand at 4180'. Capped sand with 5' of Calseal. Ran packer and tubing. Packer set at 3958'. Established injection rate of 3 BPM. Pulled tubing and packer. Ran cement retainer and tubing. Retainer set at 3955'. Cemented with 150 sacks class C neat cement, 100 sacks thickset, and tailed in with 50 sacks class C neat cement. Displaced to perfs with 40 barrels of water. Pumped 150 sacks class C with 5#/sack tuf-plug, 100 sacks thickset, and 5 sacks class C neat. Displaced with 35 barrels of water. Pumped 100 sacks class C with 2% CAC2 with 5# sand per sack, 50 sacks class C with2% CAC2 and 50 sacks class C neat cement Displaced with 6 barrels of water. Squeeze pressure 1500 psi. Pulled out of retainer and dumped 1 sack cement on tool. Pulled out of hole. WOC 12 hours. Ran 4-3/4" bit and tubing. Drilled out cement and retainer to 4102'. Tested to 1000 psi. Bled to 0 in 1-1/2 minutes. Drilled out cement to 4171'. Circulate hole clean and established injection rate of 1 BPM at 1100 psi. Pulled out of hole. Ran cement retainer and set at 3900'. Squeezed perfs with 100 sacks class C with 2% CACL and 5# sand per sack and 12 sacks class C with 2% CACL. Displaced with 1 barrel of water. Pulled out of retainer and reversed out 60 sack Pulled tubing and stinger. WOC 12 hours. Ran 4-3/4" bit and tubing. Tagged cement at 3986'. DRilled out retainer and cement to 4102'. Tested squeeze to 1000 psi. Bled to 100 psi in 30 minutes. Drilled out cement to 4171'. Tested to 1000 psi. Bled to 400 psi in 0+5-NMOCD,H 1-HOU 1-W. Stafford, HOU 1-DMF

id. I hereby certify that the Alormayon above is true and complete to the best of my snowledge and belief.

mark freeme	Assist. Admin. Analyst	DATE 1-18-83
ORIGINAL SIGNED BY JERRY SEXTON DISTRICT 1 SUPR.		JAN 20 1983

1 hour . Cleaned out seal and sand to 4250'. Circu ed hole clean. Ran in hole with packer and 2-7/8" tubing. Packer set at 3870'. Loaded with 70 bbls. packer fluid. Tested to 400 psi. Tested OK. Returned well to injection. Injecting 300 BWPD at 240 PSI.

RECEIVED JAN 1.9 1983 HOBRS

•