

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 12-1-77

5a. Indicate Type of Lease
State ☒ For ☐
5. State Oil & Gas Lease No.
B-244

SUNDARY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO CELESTOR OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE APPLICATION FOR PERMIT TO DRILL OR CELESTOR FOR SUCH PROPOSALS.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	7. Unit Agreement Name
2. Name of Operator Amoco Production Company	8. Form or Lease Name South Hobbs (GSA) Unit
3. Address of Operator P.O. Box 68, Hobbs NM 88240	9. Well No. 119
4. Location of Well UNIT LETTER C 330 FEET FROM THE North LINE AND 2310 FEET FROM THE West LINE, SECTION 8 TOWNSHIP 19-S RANGE 38-E N.M.P.M.	10. Field and Pool, or Wildcat Hobbs GSA
15. Elevation (Show whether LF, RT, GR, etc.) 3612' GL	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPER. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER ☒ Acidize	CASING TEST AND CEMENT JOBS ☐	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Propose to acidize to increase production as follows:

POH with rods and pump, lower tbq and tag TD, pull tbq. If fill is found RIH with bit or bulldog bailer and clean out to 4110'. RIH with 1 jt. tail pipe, packer unloader, and tbj., set pkr. at 3970'. Acidize the Grayburg as follows: * pump 150 gals of 15% NE HCl and 550 gals of Welchem Super A-Sol. Pump 4000 gals of 15% NE HCl. Pump 200 lbs rock salt and 70 lbs of 100 mesh salt in 200 gals of 30# gelled brine. Pump 150 gals of 15% NE HCl and 550 gals of Welchem Super A-Sol. Pump 4,000 gals of 15% NE HCl. Flush with 30 bbls fresh water. Release pkr. and POH. Install production equipment and return well to production.

* Open unloader and

0+5 NMOC, H 1-J.R. Barnett, Hon 1-F.J. Nash, Hon 1-GCC

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Eddie W. Seay TITLE AAA DATE 6-8-84

APPROVED BY Eddie W. Seay TITLE Oil & Gas Inspector DATE JUN 12 1984
CONDITIONS OF APPROVAL, IF ANY: