

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-77

5a. Indicate Type of Lease
State ☒ Fee ☐
5. State Oil & Gas Lease No.
B-244

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL ☐ GAS WELL ☐ OTHER- PXA	7. Unit Agreement Name
2. Name of Operator AMOCO PRODUCTION COMPANY	8. Farm or Lease Name South Hobbs (GSA) Unit
3. Address of Operator P.O. BOX 68 HOBBS, NEW MEXICO 88240	9. Well No. 118
4. Location of well UNIT LETTER D 330 FEET FROM THE North LINE AND 990 FEET FROM THE West LINE, SECTION 8 TOWNSHIP 19-S RANGE 38-E N.M.P.M.	10. Field and Pool, or Wildcat Hobbs GSA
15. Elevation (Show whether DF, RT, GR, etc.) 3622' KB	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐
OTHER ☐

PLUG AND ABANDON ☒
CHANGE PLANS ☐
OTHER ☐

REMEDIAL WORK ☐
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOB ☐
OTHER ☐

ALTERING CASING ☐
PLUG AND ABANDONMENT ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Propose to PXA as follows:

POH with production equipment. RIH and set cement retainers at 3800'.

Pump 150 sacks class C' cement, squeeze to 150 psi, and dump excess on retainers.

Pull up to 3500' and spot 22 bbls of 10# brine w/25# gel/bbl. Spot 25 sacks 2350-2600', spot 16 bbls 10# brine w/25# gel/bbl. Spot 25 sacks cmt 2400-2650', spot 25 bbls of 10# brine w/25# gel/bbl. Perf 300-301' w/4JSPF.

Establish circulation through 5 1/2" - 8 5/8" annulus. Pump down 5 1/2" csg 125 sacks class C' cement, squeeze to 1500 psi. Leave csg full to surface w/cement. Weld on cap and erect PXA markers.

0+5 NMOC- 1-JRB 1-FJN 1-CMH

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *Harry C. Clark*
Eddie W. Seay

TITLE Administrative Analyst

DATE 11-14-85

APPROVED BY **Oil & Gas Inspector**

TITLE

DATE

NOV 18 1985

CONDITIONS OF APPROVAL, IF ANY: