

OIL CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-73

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

34. Indicate Type of Lease	
State ☐	Fee ☐
35. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO REOPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. ☒ OIL WELL ☐ GAS WELL ☐ OTHER- PxA	7. Unit Agreement Name
2. Name of Operator AMOCO PRODUCTION COMPANY	8. Farm or Lease Name S.E. Cone - Will Terry
3. Address of Operator P.O. Box 4072, Odessa, Texas 79760	9. Well No. 1
4. Location of Well UNIT LETTER 0 990 FEET FROM THE South LINE AND 1650 FEET FROM THE East LINE, SECTION 9 TOWNSHIP 19-S RANGE 38-E NMPM.	10. Field and Pool, or Widest Hobbs GSA
15. Elevation (Show whether DF, RT, GR, etc.) 3611' GL	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPER. ☐	PLUG AND ABANDONMENT ☒
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOBS ☐	OTHER ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703.

Cut off 8 5/8" casing 14 feet below ground level. RU rathole machine and drill out cement plug from 14' to 43' and RD rathole machine. MI and RUSU 04-09-84 and drill cement from 43' to 226'. Run bit to 345' and drill cement from 345' to 580'. Clean out hole from 580' to 1050' and pull bit. Run fishtail bit and clean out and drill cement to 1138'. Run 2 7/8" tubing open ended and tag at 1136'. Pull up to 1116' and pump 900 sacks of Class "H" cement and POH. WOC. Run tubing and tag cement at 36'. Pull up to 31' and pump 20 sacks of Class "C" cement and circulate 15 sacks to pit. Cut off casing head and install PxA marker. RD and MOSU 04-15-84.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED O. M. Mitchell TITLE Sr. Admin. Analyst DATE 03-23-88
O. M. Mitchell
Eddie W. Seay
 APPROVED BY Oil & Gas Inspector TITLE _____ DATE APR 6 1988
 CONDITIONS OF APPROVAL, IF ANY:

1000

1000

1000