

OIL CONSERVATION DIVISION

P. O. BOX 2088  
SANTA FE, NEW MEXICO 87501

Form O-103  
Revised 10-1-71

|                        |  |
|------------------------|--|
| NO. OF COPIES RECEIVED |  |
| DISTRIBUTION           |  |
| SANTA FE               |  |
| FILE                   |  |
| U.S.G.S.               |  |
| LAND OFFICE            |  |
| OPERATOR               |  |

Oil Indicate Type of Lease  
State ☐ Fee ☒  
5. State Oil & Gas Lease No.

SUNDY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE APPLICATION FOR PERMIT LIT (FORM O-101) FOR SUCH PROPOSALS.)

1. OIL ☒ GAS ☐ OTHER ☐  
2. Name of Operator  
Amoco Production Company  
3. Address of Operator  
P. O. Box 68 Hobbs, NM 88240  
4. Location of Well  
UNIT LETTER D 660 FEET FROM THE North LINE AND 660 FEET FROM  
THE West LINE, SECTION 9 TOWNSHIP 19-S RANGE 38-E NMPL  
15. Elevation (Show whether DF, RT, GR, etc.)  
3604' DF  
10. County  
Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

|                                                           |                                           |                                                      |                                               |
|-----------------------------------------------------------|-------------------------------------------|------------------------------------------------------|-----------------------------------------------|
| PERFORM REMEDIAL WORK <input checked="" type="checkbox"/> | PLUG AND ABANDON <input type="checkbox"/> | REMEDIAL WORK <input type="checkbox"/>               | ALTERING CASING <input type="checkbox"/>      |
| TEMPORARILY ABANDON <input type="checkbox"/>              | CHANGE PLANS <input type="checkbox"/>     | COMMENCE DRILLING OPNS. <input type="checkbox"/>     | PLUG AND ABANDONMENT <input type="checkbox"/> |
| FULL OR ALTER CASING <input type="checkbox"/>             | OTHER <input type="checkbox"/>            | CASING TEST AND CEMENT JOBS <input type="checkbox"/> |                                               |

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Propose to squeeze all perforations, reperforate and acidize as follows:

Pull rods, pump & tbg. Run pkr & tbg w/pkr set approx 4120'. Pull pkr & tbg. Run a cmt retainer on tbg & set at 4115'. Pmp 50 sacks Class C w/.6% Halad-9, 50 sacks Class C w/1# Tuf-plug per sack, and 100 sacks Class C cmt. Run pkr on tbg & set approx 3950'. Pull pkr & tbg. Run a cmt retainer on tbg & set at 3940'. Pmp 50 sacks Class C w/.6% Halad-9, 50 sacks Class C w/1# Tuf-plug per sack, and 100 sacks Class C cmt. Drill out all cmt retainer & cmt. Test both squeezes. Drill out 4189'-4230'. Wash out & circ. Run tbg & pkr w/pkr set at 4168'. Pmp 1000 gals 15% HCL at approx 2-3 bbls per min. Spot sand from total depth to 4190'. Run csg gun & perf 4152'-88' w/4 SPF. Run pkr & tbg w/pkr set at 4110'. Pmp 1000 gals 15% HCL at 1-2 bbls per min. Pull pkr & tbg. Circ out sand. Return well to production.

0+4-NMOCD, H 1-Hou 1-Susp 1-CLF

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Cathy P. Forman TITLE Assist. Admin. Analyst DATE 11-9-81

APPROVED BY Jerry Sexton TITLE Dist. 1. Supt. DATE NOV 17 1981  
CONDITIONS OF APPROVAL: