

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-7

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.O.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease
State ☐ Fee ☒
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL ☐ GAS WELL ☐ OTHER- <u>Injection</u>	7. Unit Agreement Name
2. Name of Operator <u>Amoco Production Company</u>	8. Farm or Lease Name <u>South Hobbs (GSA) Unit</u>
3. Address of Operator <u>P.O. Box 68, Hobbs, NM 88240</u>	9. Well No. <u>83</u>
4. Location of Well UNIT LETTER <u>J</u> <u>1980</u> FEET FROM THE <u>South</u> LINE AND <u>1980</u> FEET FROM THE <u>East</u> LINE, SECTION <u>9</u> TOWNSHIP <u>19-S</u> RANGE <u>38-E</u> N.M.P.M.	10. Field and Pool or Wildcat <u>Hobbs GSA</u>
15. Elevation (Show whether DF, RT, CR, etc.) <u>3600' DF</u>	12. County <u>Dea</u>

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER <u>acidize to establish injection</u> ☒	CASING TEST AND CEMENT JOBS ☐	OTHER ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Propose to acidize to establish injection as follows:
MISU. Release inj. pkr. and POH. RIH with inj. pkr., collar locator, retrievable fluid plug and workstring. Set pkr. against blank pipe and lower pkr. to 4220. RIH with RFC valve on sandline. Breakdown the interval 4211'-4199' with 50 gals./ft. of 15% NE HCL with additives. Reset pkr. at 4170. Retrieve RFC valve and fluid plug. Flush with 25 Bbls. water. Attempt to establish injection. Release pkr. and POH with workstring and pkr. RIH with pkr. and tbg. Load backside and set pkr. at 3075. Return well to injection.

2-5, NMOCQ, H 1-J.R.B. Hou Km 21.15B 1-F.J.N. Hou Km 4.206 1-GCC 1-Petro Lewis

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Bonita Goble TITLE Administrative Analyst DATE 12-11-84

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT SUPERVISOR

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

DEC 13 1984

RECEIVED

DEC 12 1984

U.S. D.
FICE OF PRICE