STATE OF NEW MEXICO

JERGY.	CMA	MINERALS	DEPARTMENT	٠

ERGY AND MINERALS DE	PARIME
NO. OF COMIES ACCEIVED	
MOLTUBIRTEIO	
SANTA FE	
FILE	
U.\$.G.\$.	
LAND OFFICE	
OPERATOR	

CHDITIONS OF APPROVAL, IF ANYI

wo. or comics acceived	OIL CONSERVA			Form C-103	
SANTA PE	P. O. BOX 2088 SANTA FE, NEW MEXICO 87501			Revised 10-1-7	
FILE		1027100 07301	5a. Indicate Typ	e of Lease	
U.S.G.S.			State	Fee 🗌	
OPERATOR			5, State Off & G	as Lease No.	
SUNDRY NO	TICES AND REPORTS ON	WELLS			
(DO NGT USE THIS FORM FUR PROPOSALS USE "APPLICATION FOR	7. Unit Agreen et	nt Nume			
	HEA-				
Amoco Production Company	1	8. Farm or Lease Name South Hobbs (GSA) Unit			
ddress of Operator	9. Well No.				
P. O. Box 68 Hobbs, NM	85	85			
ocation of Well		10. Field and Pool, or Wildcat			
UNIT LETTER L 1980	FEET FROM THE South	LINE AND660	HODDS Gray	burg San Andr	
THE West LINE, SECTION	10 TOWNSHIP 19-S	*ANGE 38-E			
LINE, SECTION					
	15. Elevation (Show whether	DF, RT, GR, etc.)	12. County		
	Parista Paris (Call 11 11 11 11 11 11 11 11 11 11 11 11 1	Danie a CNI- i - D	Lea		
Check Appro NOTICE OF INTEN	priate Box To Indicate N гюн то:	•	t or Uther Data EQUENT REPORT OF:	:	
			677	_	
FORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	冯	TING CASING	
PORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING OPHS. CASING TEST AND CEMENT JQB		THEMHODIAGE DIE	
	_	OTHER			
OTHER					
Moved in service unit 2-1 5-1/2" casing to 500 psi. cement. Ran 4-3/4" bit a 4148'-68' and ran a base tagged with radioactive mreturned to production.	Perforated at 2100 nd drilled out to 42 gamma ray temperatur	'w/4 DPJS. Pumped 10': Perforated 40 re log. Acidized wa	d 500 sacks of Cla 079'-84', 4106'-20	ass "C" 6', and lons	
			•		
0+4-NMOCD, H 1-Hou	1-Susp 1-GPM				
hereby gently that the information above i	a true and complete to the best of	f my knowledge and belief			
H MA	1) 1//	· -		1	
. Heg // Wich	(As	s <mark>ist. Admin. Analy</mark> s	st 3-27	'- 81	
One Shand by Let Clements			<u>₽</u> ₽₩		