

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-77

5a. Indicate Type of Lease
State ☐ Fee ☒
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE APPLICATION FOR PERMIT - 17 (FORM C-101) FOR SUCH PROPOSALS.

1. OIL WELL ☐ GAS WELL ☐ OTHER- Injection	7. Unit Agreement Name
2. Name of Operator Amoco Production Company	8. Farm or Lease Name South Hobbs (GSA) Unit
3. Address of Operator P. O. Box 68, Hobbs, NM 88240	9. Well No. 78
4. Location of Well UNIT LETTER G 1980 FEET FROM THE North LINE AND 2310 FEET FROM THE East LINE, SECTION 10 TOWNSHIP 19-S RANGE 38-E N.M.P.M.	10. Field and Pool, or Wildcat Hobbs GSA
15. Elevation (Show whether DF, RT, CR, etc.) 3611' DF	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐

PLUG AND ABANDON ☐
CHANGE PLANS ☐

OTHER perforate and acidize ☒

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐
COMMENCE DRILLING CONS. ☐
CASING TEST AND CEMENT JOBS ☐
OTHER ☐

ALTERING CASING ☐
PLUG AND ABANDONMENT ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Propose to perforate and acidize to increase injection as follows:

Move in service unit and pull 2-3/8" tubing and Baker AD-1 tension packer set at 3990'. Perforate the zone I interval 4150'-4176' w/1 JSPF utilizing a hollow carrier casing gun. RIH with a retrievable bridge plug, treating packer, and unloader. Set the retrievable bridge plug at 4185'. Pull up and set the packer at 4050'. Acidize the San Andres with 2000 gals of 15% NE HCL acid and flush with 30 bbl water. Pull the retrievable bridge plug and packer. Rerun the injection equipment. Set packer at 3990'. Commence injection on a vacuum at a maximum rate of 3000 BWIPD.

0+5-NMOCD,H 1-J. R. Barnett, HOU Rm. 21.156 1-F. J. Nash, HOU Rm. 4.206 1-GCC 1-Petro Lewis

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Mary C. Clark

TITLE Assist. Admin. Analyst

DATE 4-16-84

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT 1 SUPERVISOR

APPROVED BY _____

TITLE _____

DATE APR 18 1984

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

APR 17 1956

O.C.D.
HOBBS OFFICE

APR 17 1956
HOBBS OFFICE