STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT

DISTRIBUTION		
SANTA FE		
FILE	<u> </u>	
U.S.G.S.		
LAND OFFICE		<u></u>
OPPRATOR		I _

OIL CONSERVATION DIVISION P. O. BOX 2088

Form C-103 · Revised 10-1-78

SANTA FE	SANTA FE, NEV	W MEXICO 87501	netrada 10 1 70
FILE	5a. Indicate Type of Lease		5a. Indicate Type of Lease
U.S.O.S.			State Fee X
LAND OFFICE			5. State Oil & Gas Lease No.
OPERATOR			
SUNDRY USE THIS FORM FOR PROF	Y NOTICES AND REPORTS OF POSALS TO DRILL OR TO DEEPEN OF PLUG	BACK TO A DIFFERENT REBERVOIR.	
OIL CAS WELL WELL	OTHER.		7, Unit Agreement Name
2. Name of Operator			8. Farm or Lease Name
MORRIS R. ANTWE	EIL		C. P. Bordages
3. Address of Operator	11 37 36	000/1	1
P. O. Box 2010 Hobbs, New Mexico 88241			10. Field and Pool, or Wildcat
4. Location of Well		". o o o	
UNIT LETTER O	560 FEET FROM THE South	LINE AND 1980 FEET FROM	Nadine Drinkard Ab
THE East LINE, SECTIO	28 TOWNSHIP 19	S RANGE 38E NMPM	
	(0)	DC DT CD at 1	12. County
15. Elevation (Show whether DF, RT, GR, etc.) 3581 GR		Lea	
Check A		Nature of Notice, Report or Or SUBSEQUEN	ther Data T REPORT OF:
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CABING	PLUG AND ABANDON	REMEDIAL WORK COMMENCE DRILLING OPHS. CASING TEST AND CEMENT JQB	ALTERING CASING PLUG AND ABANDONMENT
	_	OTHER	
OTHER		١ ,	
17. Describe Proposed or Completed Op work) SEE RULE 1 103.	erations (Clearly state all pertinent de	etails, and give pertinent dates, includin	g estimated date of starting any proposed
mud to 8265'. pipe 8294'. Sl Halliburton Lig and 950 sx Clas flocele. Plug	Ran logs. Ran 228 hoe joint 39.29'. (Dec 83. Cleaned out jts 5½" 17# N-80 cas Cemented @ 8265' with ng 18% salt and 1/4 # ining 5 #/sk salt and 83. operations-resume.	225 sx /sk flocele
	•		
•			
	•		
		-	
18. I hereby certify that the information	above is true and complete to the bea	t of my knowledge and belief.	
1 0/1//		Agent	7 Dec 83
DIGHED Y MIN THEKE	TITLE_	About 1	DATE
ORIGINAL SIGNED DISTRICT IS			DEC 12 1983

DEC 9 1983
HOBBS OFFICE