

STATE OF NEW MEXICO  
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION  
P. O. BOX 2088  
SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-75

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL ☒ GAS WELL ☐ OTHER ☐

7. Unit Agreement Name

Name of Operator  
SHELL WESTERN E&P INC.

8. Farm or Lease Name  
COOPER A

Address of Operator  
P.O. BOX 991, HOUSTON, TEXAS 77001

9. Well No.  
1

Location of Well  
UNIT LETTER B 330 FEET FROM THE NORTH LINE AND 2310 FEET FROM  
THE EAST LINE, SECTION 4 TOWNSHIP 20-S RANGE 37-E N.M.P.M.

10. Field and Pool, or Wildcat  
EUNICE MONUMENT (G-SA)

15. Elevation (Show whether DF, RT, GR, etc.)  
3563' DF

12. County  
LEA

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐  
REQUEST FOR EXTENSION OF  
OTHER TEMPORARY ABANDONMENT ☒

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPER. ☐ PLUG AND ABANDONMENT ☐  
CASING TEST AND CEMENT JOB ☐  
OTHER ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

WELL TEMPORARILY ABANDONED BY PULLING PRODUCTION EQUIPMENT AS REPORTED ON FORM C-103 APPROVED JANUARY 10, 1966. WE WISH TO EXTEND THIS WELL'S TA'D STATUS FOR ONE YEAR AS THIS WELLBORE IS BEING EVALUATED IN A GRAYBURG WATERFLOOD STUDY AND FOR UPHOLE POTENTIAL. WE PROPOSE TO PROPERLY TEMPORARILY ABANDON AS FOLLOWS:

1. RUN A GR/CCL LOG FROM PBTD TO SURFACE TO CONFIRM NO UPHOLE POTENTIAL EXISTS IN THE GRAYBURG.
2. RUN GAUGE RING AND JUNK BASKET TO 3600'. 35'
3. SET A CIBP @ 3550' AND CAP W/2 SX CMT (20' MINIMUM).
4. CIRCULATE INHIBITED WATER, TEST CASING TO 300 PSI, AND TEMPORARILY ABANDON.

8. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED A. J. Fore A. J. FORE TITLE SUPERVISOR REG. & PERMITTING DATE MARCH 1, 1985

ORIGINAL SIGNED BY JERRY SEXTON  
APPROVED BY DISTRICT 1 SUPERVISOR TITLE DATE

MAR - 5 1985