## NEW MEXICO OIL CONSERVATION COMMISSION

Santa Fe, New Mexico

## **MISCELLANEOUS NOTICES**

Submit this notice in triplicate to the Oil Conservation Commission or its proper agent before the work specified is tobegin. A copy will be returned to the sender on which will be given the approval, with any modifications considered
advisable, or the rejection by the Commission or its agent, of the plan submitted. The plan as approved should be
followed, and work should not begin until approval is obtained. See additional instructions in the Rules and Regulations

NOTICE OF INTENTION TO TEST CASING SHU	UT-OFF X	NOTICE OF INTENTION CHEMICALLY TREAT	N TO SHOOT OR	
NOTICE OF INTENTION TO CHANGE PLANS		NOTICE OF INTENTION OTHERWISE ALTER	TO PULL OP	
NOTICE OF INTENTION TO REPAIR WELL		NOTICE OF INTENTION		·
NOTICE OF INTENTION TO DEEPEN WELL				
Монти	ment, New Mer	ico Place	August 17, 19	36
OIL CONSERVATION COMMISSION,			Date	
Santa Fe, New Mexico.				
Gentlemen:				
Following is a notice of intentiton to do cer				
Amerada Petroleum Corporation Company or Operator	Mease			NE
of Sec. 36 , T. 19 , R.	<u>36</u> , N	. M. P. M., Mommen	<u>.                                    </u>	Fiel
LogCou	intv.			
TILL DOW		_		
		OSED PLAN OF WORK		
FOLLOW INSTRUCTIONS	S IN THE RULES A	ND REGULATIONS OF THE	COMMISSION	
6-5/8" 20# 10-thd. New Si	eamlesss cas	ng was set in this	wall at 3700! am	a
mented by the Halliburton Metho	od with 100	'a alea	The draw of the diff	···
		CAUAB.		
On m4				
Casing and fittings will be	e tested with	1200# 70000 0000	e and allowed to	
Casing and fittings will be r thirty minutes undisturbed.	e tested with	1200# pump pressur	Alam	្ <b>នt</b> ឧរ
drilled out of the casing and	e tested with	1 1200# pump pressur n pressure results	the cement will	star then
drilled out of the casing and lowed to stand undisturbed for	e tested with	1 1200# pump pressur n pressure results	the cement will	star then
drilled out of the casing and lowed to stand undisturbed for	e tested with	1 1200# pump pressur n pressure results	the cement will	star
drilled out of the casing and lowed to stand undisturbed for	e tested with	n 1200# pump pressur in pressure results it of 1200# pump pre ies. If no drop in	the cement will saure again appl pressure results	star
drilled out of the casing and lowed to stand undisturbed for	e tested with	n 1200# pump pressur in pressure results it of 1200# pump pre ies. If no drop in	the cement will saure again appl pressure results	stai then
drilled out of the casing and lowed to stand undisturbed for	e tested with	1 1200# pump pressur n pressure results	the cement will seure again appl pressure results	star then
drilled out of the casing and lowed to stand undisturbed for	e tested with	n 1200# pump pressur in pressure results it of 1200# pump pre ies. If no drop in	the cement will seure again appl pressure results	star
drilled out of the casing and lowed to stand undisturbed for	e tested with	n 1200# pump pressur in pressure results it of 1200# pump pre ies. If no drop in	the cement will seure again appl pressure results	star then
drilled out of the casing and lowed to stand undisturbed for illing will then be resumed.	e tested with	n 1200# pump pressur in pressure results it of 1200# pump pre ies. If no drop in	the cement will seure again appl pressure results	star then
drilled out of the casing and lowed to stand undisturbed for illing will then be resumed.	e tested with	1200# pump pressur in pressure results it of 1200# pump pre es. If no drop in	the cement will ssure again appl pressure results	sta then
drilled out of the casing and lowed to stand undisturbed for illing will then be resumed.  AUG 20 1936	e tested with If no drop : the same test thirty minus	n 1200# pump pressur in pressure results it of 1200# pump pre ies. If no drop in	the cement will ssure again appl pressure results	stai then
drilled out of the casing and lowed to stand undisturbed for illing will then be resumed.  AUG 20 1936	e tested with If no drop : the same test thirty minus	1200# pump pressur in pressure results it of 1200# pump pre es. If no drop in	the cement will ssure again appl pressure results	stai then
drilled out of the casing and lowed to stand undisturbed for illing will then be resumed.  AUG 20 1936	e tested with If no drop : the same test thirty minus	Amerada Petrolem  By Ja Stank	the cement will ssure again appl pressure results	star
drilled out of the casing and lowed to stand undisturbed for illing will then be resumed.  AUG 201936	e tested with If no drop : the same test thirty minus	Amerada Petrolem  By Ja Stack  Position Farm Boss	the cement will saure again appl pressure results	star then ied a the
drilled out of the casing and lowed to stand undisturbed for illing will then be resumed.  AUG 201936	e tested with If no drop : the same test thirty minus	Amerada Petrolem  By Ja Stack  Position Farm Boss	the cement will ssure again appl pressure results	star then ied a the
drilled out of the casing and lowed to stand undisturbed for illing will then be resumed.  AUG 201936	e tested with If no drop the same test thirty minus	Amerada Petrolem  By Ja Stack  Position Farm Boss	the cement will ssure again appl pressure results  im Corporation  pany or Operator  tions regarding well to	star then ied a the
drilled out of the casing and lowed to stand undisturbed for illing will then be resumed.  AUG 20 1936 Approved	e tested with If no drop the same test thirty minus	Amerada Petrolem  By January  Position Farm Boss Send communica	the cement will ssure again appl pressure results  tim Corporation  tions regarding well t	star then ied s the
drilled out of the casing and lowed to stand undisturbed for illing will then be resumed.  Approved  Except as follows:	e tested with If no drop the same test thirty minus	Amerada Petrolem  By January Boss Send communica	the cement will ssure again appl pressure results  tim Corporation  tions regarding well t	star then ied s the

## en en grande de la companya de la co

 $(x_{ij}, x_{ij}) = (x_{ij}, x_$ the second of the second of the second of (x,y) = (x,y) + (x,y) + (x,y)in the state of th