

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1940, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-12479
5. Indicate Type of Lease STATE ☐ FEE ☒
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name Graham State (NCT-F)
8. Well No. 6
9. Pool name or Wildcat MONUMENT; BLINEBRY

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL ☒ GAS WELL ☐ OTHER ☐	
2. Name of Operator Chevron U.S.A., Inc.	
3. Address of Operator P.O. Box 1150, Midland, TX 79702	
4. Well Location Unit Letter <u>P</u> : <u>330</u> Feet From The <u>South</u> Line and <u>660</u> Feet From The <u>East</u> Line Section <u>36</u> Township <u>19S</u> Range <u>36E</u> NMPM Lea County	
10. Elevation (Show whether DF, RKB, RT, CR, etc.)	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐	REMEDIAL WORK ☐
PLUG AND ABANDON ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	COMMENCE DRILLING OPNS. ☐
CHANGE PLANS ☐	PLUG AND ABANDONMENT ☒
PULL OR ALTER CASING ☐	CASING TEST AND CEMENT JOB ☐
OTHER: ☐	OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

8-28-00 Wireline set 7" CIBP @ 5570' circulated hole w/ 220 bbls. mud (10.0 ppg salt gel mud)
8-29-00 Plug #1 Cap CIBP @ 5570' w/ 30 sx cmt. calc. TOC @ 5391(179') tag @ 5418'.
9-30-00 Plug #2 Perforate @ 3780' pressure up to 1550# perforate @ 3680' pressure up to 1500#
Spot 40 sx cmt. @ 3830-3592', tag @ 3621'.
8-31-00 Plug #3 Perforate @ 3485' set pkr @ 3391' pressure up to 1500# spot 40 sx cmt.
3548-3310' tag @ 3330'.
8-31-00 Plug #4 Perforate @ 2950' set pkr @ 2826' pressure up to 1500# spot 50 sx cmt.
3014-2716' tag @ 2740'.
9-01-00 Plug #5 Spot 40 sx cmt. @ 1413' calc. TOC @ 1175'.
9-01-00 Plug #6 Spot 55 sx cmt. @ 320' to Surface.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE J. K. Ripley TITLE REGULATORY O.A. DATE 9/06/00
TYPE OR PRINT NAME J. K. RIPLEY TELEPHONE NO. (915) 687-7148

(This space for State Use)

APPROVED BY E. Gonzalez TITLE Field Rep DATE 4-13-01