| Office | T. 34 1 1 | ew Mexico | | Form C-10 | |
|--|---|--|---|---|--|
| District I | Energy, Minerals and | i Natural Resources | WELL ADING | Revised March 25, 19 | |
| 1625 N. French Dr., Hobbs, NM 87240 District II | OII COMPENSA | TION DIVISION | WELL API NO. | 5_1 <i>24</i> 70 | |
| 811 South First, Artesia, NM 87210 | South First, Artesia, NM 87210 OIL CONSERVATION DIVISION | | | 30-025-12479 5. Indicate Type of Lease | |
| District III 1000 Rio Brazos Rd., Aztec, NM 87410 | | | STATE [| FEE 🛣 | |
| District IV | Santa Fe, I | CUC / 6 IVINI | | | |
| 2040 South Pacheco, Santa Fe, NM 87505 | | | 6. State Oil & Ga | s Lease No. | |
| (DO NOT USE THIS FORM FOR PROPE DIFFERENT RESERVOIR. USE "APPLIC PROPOSALS.) | CES AND REPORTS ON DSALS TO DRILL OR TO DEE CATION FOR PERMIT* (FOR | EPEN OR PLUG BACK TO | 7. Lease Name or | Unit Agreement Name: | |
| Type of Well: Oil Well | | | Graham State (1 | Graham State (NCT-F) | |
| 2. Name of Operator Chevron U.S.A. Inc. | | | 8. Well No. | | |
| 3. Address of Operator | | | 9. Pool name or V | Vildost | |
| • | 9702 | | 9. Pool hame of V | | |
| 4. Well Location | | | MANUFAT ; BLITTES | | |
| Unit Letter :: | 330 feet from the | SOUTH line and | 660 feet fro | om the EAST lin | |
| Section 36 | Township 19 | S Range 36E | NMPM | County IFA | |
| | 10. Elevation (Show wh | | | County IEA | |
| 11. Check A | Appropriate Box to Ind | licate _l Nature of Noti | ice, Report, or Othe | r Data | |
| NOTICE OF INTI | ENTION TO: | s | UBSEQUENT RE | PORT OF: | |
| PERFORM REMEDIAL WORK | PLUG AND ABANDON | REMEDIAL WOR | | ALTERING CASING | |
| EMPORARILY ABANDON | CHANGE PLANS | | RILLING OPNS. | PLUG AND ABANDONMENT | |
| PULL OR ALTER CASING | MULTIPLE COMPLETION | CASING TEST A | ND | , LO, MADO MAILINA | |
| | | | | | |
| OTHER: | | OTHER: | | | |
| OTHER: 12. Describe Proposed or Complete of starting any proposed work). or recompilation. | d Operations (Clearly state | OTHER: | nd give pertinent dates, it | including estimated date of proposed completion | |
| 12. Describe Proposed or Complete of starting any proposed work). | d Operations (Clearly state SEE RULE 1103. For Mu 70'; CAP W/30' CMT. I CSG & 50' OUTSIDE OF C ET BALANCED CMT PLOG 1 | OTHER: e all pertinent details, ar ultiple Completions: Att PERF @ 3049' W/4 JHE CSG; TAG PLUG. SET 119'-319'; TAG PLUG. | PF. SET 100' BALANK BALANCED CMT PLUG SET BALANCED CMT | of proposed completion | |
| 12. Describe Proposed or Complete of starting any proposed work). or recompilation. POH W/TEG. SET CIEP @ 55 CMT PLOG W/50' INSIDE OF 0 1300'-1400'; TAG PLOG. SIPLOG 100'-SURF. CUT OFF | d Operations (Clearly state SEE RULE 1103. For Mu 70'; CAP W/30' CMT. I CSG & 50' OUTSIDE OF C ET BALANCED CMT PLOG 1 | OTHER: e all pertinent details, ar altiple Completions: Att PERF @ 3049' W/4 JHE CSG; TAG PLUG. SET 119'-319'; TAG PLUG. EAN LOCATION. THIS | PF. SET 100' BALANK BALANCED CMT PLUG SET BALANCED CMT | of proposed completion | |
| 12. Describe Proposed or Complete of starting any proposed work). or recompilation. POH W/TEG. SET CIEP @ 55'CMT PLUG W/50' INSIDE OF 0 1300'-1400'; TAG PLUG. SIPLUG 100'-SURF. CUT OFF VEY GARY WINK 3/14/00. | d Operations (Clearly state SEE RULE 1103. For Mu 70'; CAP W/30' CMT. IF CSG & 50' CUTSIDE OF CST BALANCED CMT PLOG 1MH, SET P&A MARKER, CI | OTHER: e all pertinent details, are altiple Completions: Attacked the completions of the completions of the completions of the completion | TALLANCED CMT PLUG SET BALANCED CMT PROCEDURE APPROVES | of proposed completion | |
| 12. Describe Proposed or Complete of starting any proposed work). or recompilation. POH W/TEG. SET CIEP @ 55' CMT PLOG W/50' INSIDE OF 0 1300'-1400'; TAG PLOG. SI PLOG 100'-SURF. CUT OFF I BY GARY WINK 3/14/00. | d Operations (Clearly state SEE RULE 1103. For Mu 70'; CAP W/30' CMT. IF CSG & 50' CUTSIDE OF CST BALANCED CMT PLOG 1MH, SET P&A MARKER, CI | OTHER: e all pertinent details, are altiple Completions: Attacked the completions of the completions of the completions of the completion | THE SET 100' BALANCE CMT PLUG SET BALANCED CMT PROCEDURE APPROVE elief. | of proposed completion | |
| 12. Describe Proposed or Complete of starting any proposed work). or recompilation. PCH W/TEG. SET CIEP @ 55' CMT PLUG W/50' INSIDE OF OR 1300'-1400'; TAG PLUG. SET PLUG 100'-SURF. CUT OFF WEY GARY WINK 3/14/00. | d Operations (Clearly state SEE RULE 1103. For Mu 70'; CAP W/30' CMT. IF CSG & 50' CUTSIDE OF CST BALANCED CMT PLOG 1MH, SET P&A MARKER, CI | OTHER: e all pertinent details, are altiple Completions: Attacked the completions of the completions of the completions of the completion | TELEPONE METERS OF THE SET 100' BALANCED CMT PLUG SET BALANCED CMT PROCEDURE APPROVES elief. | DATE3/16/00 | |
| 12. Describe Proposed or Complete of starting any proposed work). or recompilation. POH W/TEG. SET CIEP @ 55'CMT PLUG W/50' INSIDE OF 01300'-1400'; TAG PLUG. SET PLUG 100'-SURF. CUT OFF 1 | d Operations (Clearly state SEE RULE 1103. For Mu 70'; CAP W/30' CMT. IF CSG & 50' CUTSIDE OF CST BALANCED CMT PLOG 1MH, SET P&A MARKER, CI | OTHER: e all pertinent details, are altiple Completions: Attacked the completions of the completions of the completions of the completion | TELEPONE METERS OF THE SET 100' BALANCED CMT PLUG SET BALANCED CMT PROCEDURE APPROVES elief. | of proposed completion | |
| 12. Describe Proposed or Complete of starting any proposed work). or recompilation. POH W/TEG. SET CIEP @ 55' CMT PLUG W/50' INSIDE OF @ 1300'-1400'; TAG PLUG. SI PLUG 100'-SURF. CUT OFF WAR BY GARY WINK 3/14/00. THE COMPLETE OF WINK 3/14/00. | d Operations (Clearly state SEE RULE 1103. For Mu 70'; CAP W/30' CMT. IF CSG & 50' CUTSIDE OF CST BALANCED CMT PLOG 1MH, SET P&A MARKER, CI | OTHER: e all pertinent details, are altiple Completions: Attacked the completions of the completions of the completions of the completion | TELEPHO | DATE3/16/00 | |