

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs NM 88241-1980

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-12481
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	
7. Lease Name or Unit Agreement Name	
SHELL STATE "B"	
8. Well No.	5
9. Pool name or Wildcat	EUNICE MONUMENT G/SA

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/> P & A'd	
2. Name of Operator Amerada Hess Corporation	
3. Address of Operator P. O. Drawer D, Monument, NM 88265	
4. Well Location Unit Letter <u>F</u> : <u>1830</u> Feet From The <u>NORTH</u> Line and <u>1980</u> Feet From The <u>WEST</u> Line Section <u>36</u> Township <u>19S</u> Range <u>36E</u> NMPM <u>LEA</u> County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: Change status fr. PA'd to TA'd. ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Shell State "B" #5 (08-21-95 Thru 08-24-95)

Tyler Well Svc. MIRU & installed wellhead. Installed BOP. Ran bit, drill collars & tbgs. to 1,641'. Ran bit to 3,377'. Was unable to circ. w/500 psi pump press. Pulled the bit to 3,067' & broke circ. w/500 psi pump press. Ran the bit to 3,518' & tagged up cement. Circ. 260 bbls. of heavy mud out of the 9-5/8" csg. Drld. hard cmt. fr. 3,518'-3,617'. Circ. clean. Drld. hard cmt. fr. 3,617'-3,700'. Circ. clean. Press. up on 9-5/8" csg. string to 560 psi for 36 mins. Held OK. Displaced the csg. w/280 bbls. of pkr. fluid. Pulled & laid dwn the 2-7/8" work string, drill collars & bit. Removed the BOP & spool, installed the wellhead, RDMO. Cleaned the location. Well donated to unit as NMGSAU #1422. Well is currently TA'd until future use in the unit.
NMOCD Well No. 285.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Terry L. Harvey TITLE Sr. Staff Assistant DATE 09-21-95
TYPE OR PRINT NAME Terry L. Harvey TELEPHONE NO. 505 393-2144

(This space for State Use)

ORIGINAL SIGNED COPY TO BE RETURNED TO DISTRICT I OFFICE

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

This Approval of Temporary Abandonment Expires 9-1-99

SEP 26 1995

