

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

Form C-101
Revised 11-1-75

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

0+6-NMOCD-Hobbs 1-Mr. J.A. Midland
1-File 1-Laura Richradson-Midland
1-Engr LM 1-JA
1-Foreman EF 1-BB

1. Indicate Type of Lease	State ☐ Fee ☒
2. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO REPERFORATE OR PLUG BACK TO A DIFFERENT RESERVOIR. USE APPLICATION FOR PERMIT ON FORM C-1011 FOR SUCH PROPOSALS.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	7. Unit Agreement Name
2. Name of Operator Getty Oil Company	8. Farm or Lease Name Mexico U
3. Address of Operator P.O. Box 730, Hobbs, NM 88240	9. Well No. 1
4. Location of Well UNIT LETTER <u>B</u> , <u>330</u> FEET FROM THE <u>North</u> LINE AND <u>1650</u> FEET FROM THE <u>East</u> LINE, SECTION <u>8</u> TOWNSHIP <u>19S</u> RANGE <u>38E</u> N.M.P.M.	10. Field and Pool, or Wildcat See Hobbs Grayb-SA
15. Elevation (Show whether DF, RT, GR, etc.) 3616' DF	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐
OTHER ☐

PLUG AND ABANDON ☐
CHANGE PLANS ☐
OTHER ☐

REMEDIAL WORK ☐
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOBS ☐
OTHER ☐

ALTERING CASING ☐
PLUG AND ABANDONMENT ☐
OTHER ☒

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1503.

10/18/83 PBTD=4008'. Perfs @ 3827-3953, open hole 3983-4008'. Rig up. Pull rods & tbg. Ran bailer, tag @ 4006'. Dump 200# hydromite, tag @ 4001', dump 100# hydromite, tag @ 3995', dump 50#, tag @ 3994'.
10/19/83 Dump 50# hydromite, tag @ 3994', dump 100#, tag @ 3991'. Ran 128 joints 2 3/8" tbg. Set @ 3978'. Ran 2" x 1 1/2" x 12' pump. Started pumping @ 2:15 P.M. 12 x 64 SPM.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Eddie Seay
DATE October 21, 1983

TITLE Area Superintendent

DATE October 21, 1983

ORIGINAL SIGNED BY EDDIE SEAY

APPROVED BY OIL & GAS INSPECTOR

TITLE _____

DATE _____

CONDITIONS OF APPROVAL, IF ANY:

1m

OCT 26 1983

RECEIVED
OCT 25 1983
G.S.D.
HALLS OFFICE

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

0+5-NMOCD-Hobbs

1-File

1-Engr LM

1-Foreman EF

1-Laura Richardson

1-JA

5a. Indicate Type of Lease	
State ☐	Fee ☒
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT - I" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐		7. Unit Agreement Name
2. Name of Operator Getty Oil Company		8. Farm or Lease Name Mexico U
3. Address of Operator P.O. Box 730, Hobbs, New Mexico 88240		9. Well No. 1
4. Location of Well UNIT LETTER <u>B</u> <u>330</u> FEET FROM THE <u>North</u> LINE AND <u>1650</u> FEET FROM <u>East</u> <u>8</u> TOWNSHIP <u>19S</u> RANGE <u>38E</u> NMPM.		10. Field and Pool, or Wildcat <u>So. Hobbs Grayb-SA</u>
15. Elevation (Show whether DF, RT, GR, etc.) 3616' DF		12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐
OTHER ☐

PLUG AND ABANDON ☐
CHANGE PLANS ☐

REMEDIAL WORK ☐
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOBS ☐
OTHER Eliminate water entry ☒

ALTERING CASING ☐
PLUG AND ABANDONMENT ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

2/28/83 Rig up and pull rods, tubing and bridge plug. Ran bit to 4074, PB 4075. Pull bit. Prepare to plug back w/ hydromite, 29' sand and 22' hydromite.
3/1/83 Ran wire line and tagged @ 4075', FL @ 1700'. Dumped 7 ft³ of sand and filled hole to 4037'. Dumped 18 gal of hydromite to 4028'. Ran tbq to 3968', SN @ 3947'.
3/2/83 Ran pump 2" x 1 1/2" x 12'. Rig down unit.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Donald J. Steiner TITLE Area Superintendent DATE March 3, 1983
J. D. Crockett

APPROVED BY J. M. ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

TITLE _____ DATE MAR 7 1983

CONDITIONS OF APPROVAL, IF ANY: