

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT
SUNDRY NOTICES AND REPORTS ON WELLS

SUBMIT IN TRIP
(Other instructions
reverse side)

E-
re-

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO.

LC-029519(A)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

B.V. Lynch "A" Fed

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Lynch Yates-Seven Rivers

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec 34, T-20-S, R-34-E

12. COUNTY OR PARISH

13. STATE

Lea

NM

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

OLSEN ENERGY, INC.

3. ADDRESS OF OPERATOR

16414 San Pedro, Suite 470, San Antonio, Texas 78232

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

Unit J - 2310' FSL & 2310' FEL

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREAT

MULTIPLE COMPLETE

FRACTURE TREATMENT

ALTERING CASING

SHOOT OR ACIDIZE

ABANDON*

SHOOTING OR ACIDIZING

ABANDONMENT*

REPAIR WELL

CHANGE PLANS

(Other)

(Other) Deepen and Run Casing

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Start deepening operation 9-19-89. Drill from old TD of 3721' to 3916'. Run DLL/MLL and Z-Densilog/CNL on 9-21-89. Run 5½", 15.5# & 17# LT&C J-55 used casing on 9-22-89. Cement with 200 sacks 50-50 Pozmix with 2% gel, ¼# Flocele per sack & 3% salt. Plug down at 7:15 p.m. CT 9-22-89. On 10-3-89 perforate 3700', 3702', 3710½', 3711', 3720', & 3720½'. Acidize w/200 gals 15% NEFE Acid. Swab Dry. 10-4-89 Acidize w/2000 gals MCA acid. Ball out. Swab dry w/show of oil. Frac w/8000 gals 50/50 CO₂ foam w/12,000# 20-40 sand. Flow & swab back load. Put well on pump 10-6-89. Well test 10-9-89 - 6 BO, 36 BW, gas nil.

18. I hereby certify that the foregoing is true and correct

SIGNED Link Monteb

TITLE Dril'g & Prod'n Manager

DATE 10-12-89

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

ACCEPTED FOR RECORD

OCT 23 1989
SJS

*See Instructions on Reverse Side

CARLSBAD, NEW MEXICO