ONDITIONS OF APPROVAL, IF ANYI) . 6 COT-

| STATE OF NEW MEXICO | |
|---|---|
| NERGY AND MINERALS DEPARTMENT OIL CONSERVATION DIVISION P. O. BOX 2088 SANTA FE, NEW MEXICO 87501 | Form C-103 Revised 10-1-7 |
| U.S.O.S. LAND OFFICE OPERATOR | Su. Indicate Type of Lease State Fee Fee 5. State Off & Gas Lease No. |
| SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR EXCESSALS TO CRILL OR TO DEEPIN OR PLUG BACK TO A DIFFERENT RESERVOIR. | 7, Unit Agreement Name |
| Amoco Production Company | 8. Farm or Lease Name South Hobbs (GSA) Unit |
| P. O. Box 68 Hobbs, NM 88240 | 9. Well No. 88 10. Field and Pool, or Wildcat |
| UNIT LETTER J , 1650 FEET FROM THE SOUTH LINE AND 2310 FEET F | |
| THE East LINE, SECTION 10 TOWNSHIP 19-S RANGE 38-E NM 15, Elevation (Show whether DF, RT, GR, etc.) | 12. County Lea |
| Check Appropriate Box To Indicate Nature of Notice, Report or NOTICE OF INTENTION TO: | |
| PLUG AND ABANDON REMEDIAL WORK COMMENCE DRILLING OPNS CHANGE PLANS CASING TEST AND CEMENT QB | ALTERING CASING PLUG AND ABANDONMENT |
| Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, inclusions) SEE RULE 1103. | ding estimated date of starting any proposed |
| Propose to increase production by the following method: | |
| Pull pump and ran a packer and set at 3950'. Run Gamma Ray and temp base log from 3900'-4170'. Acidized well with 4000 gallons and flus of water. Pull tubing and return to production. | perature survey sh with 60 barrels |
| | |
| 0+4-NMOCD, H 1-Hou 1-Susp 1-GPM | |
| . I hereby certify that the information above is true and complete to the best of my knowledge and belief TITLE Admin. Analyst | DATE 4-27-81 |
| Orig. Signed Sy | DATE |