

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs NM 88241-1980

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-20193
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	B-3114-7
7. Lease Name or Unit Agreement Name	NORTH MONUMENT G/SA UNIT BLK. 18
8. Well No.	5
9. Pool name or Wildcat	EUNICE MONUMENT G/SA
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER INJECTION WELL	
2. Name of Operator Amerada Hess Corporation	
3. Address of Operator P.O. DRAWER D, MONUMENT, NM 88265	
4. Well Location Unit Letter <u>E</u> : <u>2322</u> Feet From The <u>NORTH</u> Line and <u>992</u> Feet From The <u>WEST</u> Line Section <u>2</u> Township <u>20S</u> Range <u>36E</u> NMPM LEA County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: CONVERT TO INJECTION WELL. ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

NMGSAU #1805 (12-10-96 THRU 12-18-96)

MIRU TYLER WELL SVC. & STAR TOOL. TOH W/PROD. EQUIP. RMV. WELLHEAD & INSTALL BOP. TOH W/122 JTS. OF TBG., TAC, 1 JT. SALTA LINED TBG. & SN. TIH W/BIT. BIT SUB & 50 JTS. TBG. BIT @ 1,540'. TIH W/75 JTS. OF 2-7/8" TBG. & TAG TOP OF FILL @ 3,837'. RU POWER SWIVEL & INSTALL STRIPPER HEAD. CLEAN OUT FILL FR. 3,827' TO 3,857'. TOH W/125 JTS. TBG., BIT SUB & BIT. TIH W/MODEL "G" RBP. SN & 122 JTS. OF TBG. SET RBP @ 3,774'. CIRC. CSG. CLEAN. TST. CSG. TO 560# FOR 30 MINS. HELD OK. LATCH ONTO RBP & TOH W/122 JTS. OF TBG., SN & RBP. TIH W/BIT. BIT SUB. D.C. 'S. SN & 64 JTS. OF TBG. TO 2,211'. TIH W/54 JTS. OF TBG. RU POWER SWIVEL & INSTALL STRIPPER HEAD. PUMP 110 BBLs. FW TO EST. CIRC. DRILL CMT. FR. 3,857'-3,859'. DRILL CMT. RETAINER FR. 3,859'-3,863'. DRILL CMT. FR. 3,863'-3,889'. TOH W/4 JTS. TBG. TO 3,790'.
(CONTINUED)

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Terry L. Harvey TITLE SR. STAFF ASSISTANT DATE 12-19-96
TYPE OR PRINT NAME TERRY L. HARVEY TELEPHONE NO. 505-393-2144

(This space for State Use)

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

JCRN