## STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT

49 37 COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
111.2	
U.3.G.5.	
LAND OFFICE	L
ROTAPSTO	

## OH CONSERVATION DIVISION

## 31 CO-IES MCCCIAED	OIL COM	DELLA MILOM DIA12	1014	
DISTRIBUTION	P. O. BOX 2088			Form C-103 ·
SANTA FE	SANTA	FE, NEW MEXICO 8750	1	Revised 10-1-7
111.2	<u> </u>		5a. Indicate	Type of Leuse
U.3.G.S.	4		State [	Foo T
LAND OFFICE	-}			& Gas Lease No.
OPERATOR	J		E-523	
SUNDR	Y NOTICES AND REP	ORTS ON WELLS EN OF PLUG BACK TO A DIFFERENT RI		
OIL X WELL	OTHER-	,	7. Unit Agre	eement Nume
. Name of Operator			8. Farm or L	_ease Name
MINERALS, INC.		Bass S	State	
Address of Operator			9. Well No.	
P.O. Box 1320, Hobbs,	, New Mexico 882	240	1	
. Location of Well			10. Field ar	nd Pool, or Wildcat
UNIT LETTER C	560 FEET FROM THE _	North LINE AND 2.08	O FEET FROM Salt 1	_ake Yates
THE West LINE, SECTION	on 18 TOWNSHI	12 20S RANGE 33	E NMPM.	
,				
		how whether DF, RT, GR, etc.)	12. County	
	3525 GL		Lea	
PERFORM REMEDIAL WORK  LMPORABILY ABANDON  VULL OR ALTER CASING	PLUG AND AI	BANDON X REMEDIAL WORK COMMENCE DRILLING CASING TEST AND CEN OTHER	OPNS. P	LUG AND ABANDONMENT
Describe Proposed or Completed Opwork) SEE RULE 1103.	perations (Clearly state all p	pertinent details, and give pertinen	it dates, including estimated dat	e of starting any proposed
Propose to plug an	ıd abandon as foll	ows:		
		Squeeze overall perfo ontaining 2% gel and 3		8' with 50
<ol><li>Fill remainder salt to surfac</li></ol>	of hole with 510	sacks of 50-50 Pozm	ix containing 2% gel	and 3%
3. Erect P&A mark	er and restore we	ell pad to normal conf	tour.	
				·
·			413SION MUST BE NO	ration

ic. I hereby certify that the information above is true and complete to the best of my knowledge and belief. Vice President, Engr. Orig. Signed by JUN 15 1982 Les Clements Oil & Gas Insp.

HOBBS OFFICE