

COPIES RECEIVED		
TRIBUTION		
FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

1. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
B-1626	
7. Unit Agreement Name	
8. Farm or Lease Name	
State "V"	
9. Well No.	
5	
10. Field and Pool, or Allotment	
Monument-McKee	
12. County	
Lea	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- Dry Hole
2. Name of Operator
Amerada Hess Corporation
3. Address of Operator
Drawer "D", Monument, New Mexico 88265
4. Location of Well
UNIT LETTER <u>G</u> <u>1980</u> FEET FROM THE <u>North</u> LINE AND <u>1830</u> FEET FROM THE <u>East</u> LINE, SECTION <u>36</u> TOWNSHIP <u>19-S</u> RANGE <u>36-E</u> NMPM.
15. Elevation (Show whether DF, RT, GR, etc.)
3603' DF

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Well was drilled as a dry hole and T.A. 3-1-63.
Cement plugs were set in open hole and in 7-5/8" casing when well was abandoned.
Plan to: Set 100' cement plug at top of Salt or approx. 1100'.
Set 10' cement plug with permanent dry hole marker at surface.
Plug and abandon.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE Supver., Admin. Services DATE 5-28-74
APPROVED BY [Signature] TITLE DATE
CONDITIONS OF APPROVAL, IF ANY: