

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-103
Revised March 25, 1999

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-025-20607
1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input checked="" type="checkbox"/> Other <input type="checkbox"/>		5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
2. Name of Operator Chevron USA, Inc.		6. State Oil & Gas Lease No.
3. Address of Operator 15 Smith Rd. Midland, Tx 79705		7. Lease Name or Unit Agreement Name: North Wilson Deep Unit
4. Well Location Unit Letter <u>O</u> : <u>660'</u> feet from the <u>SOUTH</u> line and <u>1980'</u> feet from the <u>EAST</u> line Section <u>31</u> Township <u>20-S</u> Range <u>36-E</u> NMPM <u>LEA</u> County		8. Well No. 1
		9. Pool name or Wildcat Osudo Marrow Gas
10. Elevation (Show whether DR, RKB, RT, GR, etc.)		

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

1. Set 7 CIBP @ 11,300 spot 25sx plug fr/11300-11200(MorrowGas) Tag @ 11189
2. Displace hole w/MLF 9.5# Brine w/25# Gel P/BBL,
3. Spot 40sx plug 10150-9950(Lower Bone Springs)
4. Spot 40sx plug 7950-7750(Upper Bone Springs)
5. Perf 4 holes @ 5400 unable to sqz spot 50sx plug fr/5400-5200(9 5/8 shoe, Delaware) Tag @
6. Perf 4 holes @ 3600-3300(B-salt, Yates) unable to sqz spot 70sx plug fr/3600-3300 Tag @ 3198
7. Perf 4 holes @ 1900-1700 (T-salt) sqz perf w/100sx Tag @ 1651
8. Perf 4 holes @ 375 circ cmt fr/375 to surf w/135sx Tag @ surf
9. Install dry hole marker 11-15-02

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE [Signature] TITLE MANAGER/SUNSET DATE 11-15-02

Type or print name Jimmy BAGLEY Telephone No. 915 520 8756

(This space for State use)

APPROVED BY GARY W WINK TITLE OC FIELD REPRESENTATIVE II/STAFF MANAGER DATE FEB 01 2003

Conditions of approval, if any

GWV