Submit 3 Copies to Appropriate District Office

## State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

DISTRICT I P.O. Box 1980, Hobbs, NM 88240

O

IL CONSERVATION DIVISION 310 Old Santa Fe Trail, Room 206 Santa Fe, New Mexico 87503	<b>WELL API NO.</b> 30-025-21258	
	5. Indicate Type of Lease STATE	FEE
	6. State Oil & Gas Lease No.	

DISTRICT II Santa Fe, New Mexico 87503	30-025-21258
P.O. Drawer DD, Artesia, NM 88210	5. Indicate Type of Lease
DISTRICT III 1000 Rio Brazos Rd., Aziec, NM 87410	STATE X FEE 6. State Oil & Gas Lease No.
1000 NO DIRAK KIL, AMEC, NM 0/410	E-8913
SUNDRY NOTICES AND REPORTS ON WELLS	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"	7. Lease Name or Unit Agreement Name
(FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL GAS GAS	]
WELL WELL OTHER  2. Name of Operator	State E 8. Well No.
Stevens & Tull, Inc.	a. Well 140.
3. Address of Operator	9. Pool name or Wildcat
P.O. Box 11005, Midland, TX 79702	Wildcat
Unit Letter D : 660 Feet From The North Line and	660 Feet From The West Line
Can bear Feet From the ROLLIT Fair and	Territoria in Wast
Section 20 Township 20S Range 36E  10. Elevation (Show whether DF, RKB, RT, GR, etc.)	NMPM Lea County
10. Elevation (Show whether Dr., RKB, R1, GR, etc.)	
11. Check Appropriate Box to Indicate Nature of Notice,	Report, or Other Data
	BSEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	X ALTERING CASING
TEMPORARILY ABANDON	NG OPNS. UPLUG AND ABANDONMENT
PULL OR ALTER CASING CASING TEST AND C	CEMENT JOB
OTHER: OTHER: Begi	n Reentry x
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, i	recluding estimated date of starting any proposed
work) SEE RULE 1103.	and the state of t
3/18/96 - Rig up pulling unit - RIH w/12 1/4" bit -	
Drill/Wash to 250' and found 10' cement p	lug.
3/20/96 - Found cement plug st 314' - 342' - 9 5/8"	casing stub at 3521
Try to tie back 9 5/8" casing - unable to	
	- /- 11
3/26/96 - Cut window inside 9 5/8" casing. RIH w/8 still have not hit cement plug - hole is:	
plastic buckets	turi or crash - marking
•	
I hereby certify that the information above is true and complete to the best of my knowledge and belief.	
SIGNATURE MICHAEL MATTHELL CONSULTIN	ng Engineer DATE 4/1/96
by Sonfie Metral	
TYPE OR PRINT NAME	TELEPHONE NO.
(This space for State Use) OF 10 ments of Others by The Art SERVICE	
(implement are only O. M.	JUN 11 1996

APPROVED BY ... CONDITIONS OF APPROVAL, IF ANY:

