

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE
(Other instructions on re-
verse side)COPY TO O. C. C.
Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

5. LEASE DESIGNATION AND SERIAL NO.

LC-069944

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

LITTLE EDDY UNIT

8. FARM OR LEASE NAME

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

WILDCAT

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

5-20-33 NMPM

12. COUNTY OR PARISH

LEA

13. STATE

NM

1.

OIL
WELL☐GAS
WELL☐

OTHER

DRY HOLE

2. NAME OF OPERATOR

3. ADDRESS OF OPERATOR

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface

660 FSL x 1984.9' FWL, Sec. 5 (Unit N, SE 1/4 SW 1/4)

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, OR, etc.)

3565 R.D.B.

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETION

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(Note: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones perti-
nent to this work.)

Well was drilled to a depth of 14895' without encountering commercial quantities of oil or gas. Form 9-331 dated 6-2-66 reported Devonian attempt and back to PAD 11525. Wolf camp test & work: Set CIBP @ 11492'. Perf. 11184-88, 92-46, 11216-24, 41-48, 11370-76, 11456-64 w/ 2 1/2 SPF. Acidized w/ 5000 gal. Fraced w/ 30,000 gal Oil, 13,250' Sand, 2,250' Glass beads. Never recovered load. Abandoned by spotting 25 sz. cement plug from 11,107 - 10,900. Set CIBP @ 9250. Bone Springs: Perforated intervals 9136-46, 78-88' w/ 2 1/2 SPF. Acidized w/ 5000 gallons. Fraced w/ 20,000 gal brine, 25000' Sand 2000' glass beads. Never recovered loadwater. Abandoned by spotting 25 sz. cement plug 9200-9000.

It is now proposed to P&A as follows: Cut and pull 5 1/2" from Free Point; Spot 58 sz plug in and out of 5 1/2" stub; 35 sz in and out of 9 7/8" (55 sz) from 5586-5486; Shoot and pull 9 7/8" from Free Point; 1800' plug from 2900' to 1100' (approx 1175 sz.); 10 sz at surface and red P&A marker.

Restore ground to contour and make final cleanup.

18. I hereby certify that the foregoing is true and correct

SIGNED

William

TITLE

Area

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

7-7-66

APPROVED

JUL 11 1966

J. L. GORDON.
ACTING DISTRICT ENGINEER

*See Instructions on Reverse Side

0-4-USGS-N
1-INSB
1-BUSP
1-BOY1-PERRY R. BASS
1-STATE LAND
1-US BORAX