

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

OIL CONSERVATION DIVISION

DISTRICT I
P.O. Box 1980, Hobbs NM 88241-1980

2040 Pacheco St.
Santa Fe, NM 87505

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

WELL APINO. 30-025-22006
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name South Hobbs (GB/SA) Unit
8. Well No. 97
9. Pool name or Wildcat Hobbs Grayburg - San Andres

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER Injection
2. Name of Operator Altura Energy Ltd.
3. Address of Operator P.O. Box 4294 Houston, Texas 79210-4294
4. Well Location Unit Letter <u>P</u> : <u>990</u> Feet From The <u>South</u> Line and <u>990</u> Feet From The <u>East</u> Line Section <u>10</u> Township <u>T-19-S</u> Range <u>R-38-E</u> NMPM <u>Lea NM</u> County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) DF 3598'

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 5-1/2" CIBP set @ 4012' on 12/3/97.
- Circulate hole w/9.5# MLF.
- Spot 25 Sxs "Class C" cmt on top of CIBP from 4012'-3765'.
- Perf 4 holes @ 2800', set Ret @ 2700', Sqz 30 Sxs under & cap w/25 Sxs.
- Perf 4 holes @ 1750', set Ret @ 1650', Sqz 30 Sxs under & cap w/25 Sxs.
- Spot 25 Sxs cmt @ 366'.
- Spot 10 Sxs cmt @ 30' to surface.
- Cut off well head, install dry hole marker.

****Notify NM OCD 24 hrs prior to rigging up****

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Roger Massey TITLE Senior P&A Supervisor DATE 12/9/97

TYPE OR PRINT NAME Roger Massey TELEPHONE NO. 915-530-0907

(This space for State Use)

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: _____

ORIGINAL SIGNATURE BY CHRIS WILLIAMS
SUPERVISOR

DEC 30 1997