

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

## OIL CONSERVATION DIVISION

2040 Pacheco St.  
Santa Fe, NM 87505

WELL API NO. 30-025-22191
Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
State Oil & Gas Lease No. 17383
Lease Name or Unit Agreement Name Mallard Alves
Well No. 1
Pool name or Wildcat North Osudao Morrow

<b>SUNDRY NOTICES AND REPORTS ON WELLS</b> (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER	
Name of Operator Nadel and Gussman Permian, L.L.C.	
Address of Operator 601 N. Marienfeld, Suite 508, Midland, TX 79701	
Well Location Unit Letter P : 660 Feet From The South Line and 990 Feet From The East Line Section 6 Township 20S Range 36E NMPM Lea County	
Elevation (Show whether DF, RKB, RT, GR, etc.) 3635 GR	

11

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

### NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐  
OTHER: ☐

### SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐  
CASING TEST AND CEMENT JOB ☐  
OTHER: ☐

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Notify Hobbs NMOCD 24 hours before beginning work.
2. Free point, cut and recover tbg at approx. 7975'.
3. Set cmt retainer at 7950' and cmt w/100 sxs neat.
4. Circulate well with 9.5 ppg fluid.
5. Spot and tag a 25 sx plug across 9-5/8 csg, shoe at 5300'-5150'.
- \* 6. Spot 35 sx plug across base of salt from 3200'-3100'.
7. Spot 35 sx plug across surface csg shoe from 500'-400'. WOC and tag cement.
8. Spot 10' surface plug. Cut off wellhead.
9. Erect standard 6' dry hole marker, remove all surface equip, deadmen, clean, level and reseed location.

100' PLUG F/1840'-1740' (TOP OF SALT)

THE COMMISSION MUST BE NOTIFIED 24 HOURS BEFORE THE BEGINNING OF PROPOSED OPERATIONS FOR THE C-103 TO BE APPROVED.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Kem E. McCready

TITLE Operations Engineer

DATE 4/3/02

TYPE OR PRINT NAME Kem E. McCready

TELEPHONE NO. 915/682-4429

(This space for State Use)

APPROVED BY

ORIGINAL SIGNED BY

DATE

CONDITIONS OF APPROVAL, IF ANY:

GARY W. WINK

OC FIELD REPRESENTATIVE II/STAFF MANAGER

APR 11 2002

# NADEL AND GUSSMAN PERMIAN

**Mallard Alves #1**  
 660' FSL, 990' FEL, Unit P, Sec 6, 20S, 36E, Lea County, NM  
 API # 30 - 025 - 22191

Elev: 3635', KB = 3650'

## Recommended P&A

