

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-22191
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name Mallard Alves
8. Well No. 1
9. Pool name or Wildcat North Osudo Morrow

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER	
2. Name of Operator J&G Enterprise Ltd., Co.	
3. Address of Operator PO Box 100, Artesia, New Mexico 88210	
4. Well Location Unit Letter <u>P</u> : <u>660</u> Feet From The <u>South</u> Line and <u>990</u> Feet From The <u>East</u> Line Section <u>6</u> Township <u>20S</u> Range <u>36E</u> NMPM <u>Lea</u> County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) <u>3635 GR</u>	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <u>Re-entry</u> <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

08-23-95 Clean location. Dig out cellar. Remove dry hole marker. Install casinghead.

08-24-95 RU W.O. Rig & Reverse Unit. Start drlg. Plug to re-enter well. Clean out to top 7" csg. ran 7" csg. liner. Tie into csg. & cement w/200 sks. Cl. "C". Circ. to top liner up in 9-5/8" csg. Drill up cement ret. cut over 2 packers. Clean out to top 4-1/2" liner 10,986'. Drill out liner to PSTD 12,298'. Ran pkr. w/tailpipe. Treat old perfs 12,100' to 12,258' w/2000 gal. 7-1/2% NEFE. Swabb well in. Existing perfs: 12,100 to 104 - 12,138 to 150' 12,205 to 207 - 12,230 to 238 - 12,254 to 258 - 64 holes.

10-04-95 Well SI. Waiting on gas line.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE J. T. Jackson TITLE President DATE 10-5-95

TYPE OR PRINT NAME J T Jackson TELEPHONE NO. 746-9680

(This space for State Use)

ORIGINAL FILED IN JERRY SEXTON
DISTRICT I SECRETOR

OCT 11 1995

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

10/1/95

