NO, OF COPIES RECEIVED			Form C-103
DISTRIBUTION			Supersedes Old
SANTA FE		ERVATION COMMISSION	C-102 and C-103
FILE		CRYATION COMMISSION	Effective 1-1-65
U.S.G.S.			
			5a. Indicate Type of Lease
OPERATOR			State Fee X
of Envior			5. State Oil 5 Gas Lease No.
SUNE	DRY NOTICES AND REPORTS ON PROPOSALS TO DRILL OR TO DEEPEN OR PLUG ATION FOR PERMIT	WELLS	
(DO NOT USE THIS FORM FOR I USE "APPLIC	PROPOSALS TO DRILL OR TO DEEPEN OR PLUG ATION FOR PERMIT -** (FORM C-101) FOR SUG	BACK TO A DIFFERENT RESERVOIR.	
1.		· ·	7. Unit Agreement Name
	OTHER-		
2. Name of Operator	8. Farm or Lease Name		
Mallard Exploration, Inc.			Alves
3. Address of Operator			9. Well No.
200 Wilco Building	#1		
4. Location of Well		······································	10. Field and Pool, or Wildcat
UNIT LETTER P	660 FEET FROM THE South	990	North Osudo Morrow
THELINE, SEC	TION 6 TOWNSHIP) RANGE NM	₽M. (()))))))))))))))))))))))))))))))))))
mmmmmmm			
15. Elevation (Show whether DF, RT, GR, etc.) 3,648' DF			12. County
$\frac{16}{16}$			Lea Allllll
Check	Appropriate Box To Indicate N	ature of Notice, Report or	Other Data
			INT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING
TEMPORABILY ABANDON		COMMENCE DRILLING OPNS.	PLIG AND ABANDONMENT
PULL OR ALTER CASING	CHANGE PLANS	CASING TEST AND CEMENT JOB	
		OTHER	
OTHER			
	Operations (Clearly state all pertinent deto		

Began Plug & Abandonment procedure on 8-4-76. Set Baker retainer @ 10,900' on top of two Baker "F" permanent type packers. Pumped 100 sx Class H cmt w/0.5% HR-4/100.sx cmt below retainer, into & across perfs. Shot 7" @ 5700'; pulled 176 jts (1408') 7" csg, spotted 36 sx plug from 5750' to 5650' (50' in 7" & 50' out).* Pulled up to 5270', spotted 45 sx plug from 5270' to 5170' (9-5/8" shoe plug). A pipe recovery log was run inside 9-5/8" csg to 3,000'. The results were, pipe was bonded from 640' to surface (13-3/8" set to 407'); therefore, no 9-5/8" csg was pulled. Spotted 60 sx plug from 500' to 350' inside 9-5/8" csg, spotted 10' plug at surface. Welded plate on 13-3/8" csg and installed dry hole marker, cleaned and levelled location, & filled pits. All cmt plugs were Class "H" Cement w/.5% HR-4 per sack. Mud weight was 9.5 ppg. Completed P&A work on 8-19-76.

"After recovery of 1408' of 7" csg, there was 9,937' of 7" csg left in hole. A total of 1,411' of 4-1/2" liner was also left in the hole.

18. I hereby certify that the information above is true a		9-21-76
Contract 1 by		NOV SU SA
PPROVED BY	TITLE	DATE