

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.L.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-73

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. ☐ OIL WELL ☒ GAS WELL ☐ OTHER- Re-Entry

2. Name of Operator
Chama Petroleum Company

3. Address of Operator
P.O. Box 31405 Dallas, Texas 75231

4. Location of Well
UNIT LETTER A 660 FEET FROM THE North LINE AND 660 FEET FROM
THE East LINE, SECTION 34 TOWNSHIP 20S RANGE 35E NMPM.

5a. Indicate Type of Lease
State ☐ Fee ☒

5. State Oil & Gas Lease No.
V-285

7. Unit Agreement Name

8. Form or Lease Name
Hot Tamale State

9. Well No.
1

10. Field and Pool, or Wildcat
S.E. Lea

12. County
Lea

15. Elevation (Show whether DF, RT, CR, etc.)
3680' GL

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

TEMPORARILY ABANDON ☐

PULL OR ALTER CASING ☐

OTHER ☐

PLUG AND ABANDON ☐

CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐

COMMENCE DRILLING OPER. ☐

CASING TEST AND CEMENT JOB ☐

OTHER Activity ☒

ALTERING CASING ☐

PLUG AND ABANDONMENT ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703.

- 11/29/85: Set cattle guard. Clear location. Dug out cellar and work pit. RU pulling unit. Remove P & A marker. Cut off 9-5/8" csg. Install 9-5/8" csg riser and WH flange to surface. Fill in cellar. SDFN.
- 11/30/85: Finished MI and RU reverse equipment. Install BOP. Drill out surface cmt plug. Continue drilling to top of cmt at 5321'.
- 12/1/85: Pressure test 9-5/8" csg to 1500# for 30 mins, OK. Drill and wash out heavy mud and cmt stringers to good cmt at 5454'. Drld out of cmt at 5576'. Washing out heavy mud at 5650'.
- 12/2-5/85: Continue drlg out cmt stringers, viscous mud and barite to TD at 14,968'.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Jerry Sexton TITLE Regulatory & Production DATE 12/6/85

ORIGINAL SIGNED BY JERRY SEXTON

APPROVED BY DISTRICT SUPERVISOR

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

DEC 17 1985