Girlie on New Mexico	
ENERGY AND MINERALS DEPARTMENT	
O. CONSERVATION DIVISION	Form C-103 .
P. O. BOX 2088 SANTA FE NEW MEXICO 97501	Revised 10-1-78
SANTA FE, NEW MEXICO 87501	
U.s.o.s.	Sa. Indicate Type of Lease State X Foo
LAND OFFICE	
OPERATOR	5, State Oil & Gas Lease No.
	E-5886
SUNDRY NOTICES AND REPORTS ON WELLS 100 NOT USE THIS FORM FOR PROPOSALS TO DRILL ON TO DEEPEN OF PLUG BACK TO A DIFFERENT RESERVOIR. 100 NOT USE TIAPPLICATION FOR PERMIT - " FORM C-1011 FOR SUCH PROPOSALS.]	
	7, Unit Agreement Name
Name of Operator	West Pearl Queen Unit
° GULF OIL CORPORATION	
Address of Operator	9. Well No.
P. O. Box 670, Hobbs, NM 88240	164
Location of Well	10. Field and Pool, or Wildcat
UNIT LETTER F . 1325 FEET FROM THE NORTH LINE AND 2635 FEET FROM	Pearl Queen
UNIT LETTER	
THE West LINE, SECTION 32 TOWNSHIP 198 MANGE 35E NAMED	
THE WEST LINE, SECTION 32 TOWNSHIP TO RANGE 332 NEPM.	
15. Elevation (Show whether DF, RT, GR, etc.)	12. County
3726' GL	Lea
	D
Check Appropriate Box To Indicate Nature of Notice, Report or Ot	
NOTICE OF INTENTION TO: SUBSEQUEN	REPORT OF:
CAFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
EMPORABILY ABANDON X	PLUG AND ABANDOHMENT
ULL OR ALTER CABING CHANGE PLANS CASING TEST AND CEMENT JQB	
OTHER	
OTHER	
. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including	estimated date of starting any proposed
work) SEE RULE 1103.	, , , , ,
to the first term of the first	0.4 GIPD -4 /7/51.
Kill well if necessary with 8.6# GKF. POH with rods, pump & tubing.	Set CIBP at 4/45;
pressure test casing & CIBP to 500#. Circulate with 8.6# brine water	er + 0.0% lietolite
KW 37 and $10\#/150$ bbl Tretolite K 470. ND BOP, NU wellhead. Wareho	ouse rous & pump.
•	•
	·

Thereby certify that the information above is true and complete to the boat of my knowledge and belief.

Area Engineer

JUL 17 1980

MOITIONS OF APPHOVAL, IF ANY