OIL CONSERVATION DIVISION DISTRIBUTION SANTA FE FILE DIL CONSERVATION DIVISION P. O. BOX 2088 SANTA FE, NEW MEXICO 37501	Form C-103 Revised 10-1-73
VILE U.S.O.S. LAND OFFICE OPERATOR	Sa, indicate Type of Lease State X Fee S. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DAILL OR TO DECEME OR PLUG BICK TO A DIFFERENT RESERVOID OIL CAR WELL CALL OF THE COMMENT	7. Unit Agreement Nume
Amoco Production Company Address of Operator	8. Farm or Lease Name State "A"
P. O. Box 68 Hobbs, NM 88240	9. Well No. 41 10. Floid and Pool, or Wildcat
UNIT LETTER	Bowers - Seven Rivers
15. Elovation (Show whether DF, RT, GR, etc.) 3612 KB Check Appropriate Box To Indicate Nature of Notice, Report	Lea
SUBS	EQUENT REPORT OF:
- CARPORN REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK - COMMENCE DRILLING OPNS. - COMMENCE DRILLING OPNS. - CASING TEST AND CEMENT JOB - OTHER	ALTERING CASING
<ul> <li>OTHER</li> <li>Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, work) SEE RULE 1103.</li> </ul>	· · · · · · · · · · · · · · · · · · ·

Propose to permanently PxA the subject well. MI-RUSU. Kill well. POH w/production equipment. RIH w/CIBP and set at 3000'. Cap w/35' Class "C" cement. Fill hole with 73 bbls. 10# brine w/25# gel/bbl. Pull up to 2600' and spot 25 sacks Class "C" neat across 2600-2400'. Top of cement behind 5-1/2" casing is a 2520' per CBL. POH. RIH and perf 4 holes, 90° phasing at 500'. Rig up to pump down bradenhead and establish circulation between 5-1/2" and 8-5/8" casings. Once circulation established, pump 200 sx Class "C" neat cement and circulate to surface. Cap well and erect PxA marker RD-MOSU.

ORIGINAL SIGNED BY JERRY SEXTON OVER BY DISTRICT I SUPERVISOR OUTIONS OF APPROVAL, IF ANY:	TITLE	JAN 1 3 1987
	Administrative Analyst	DATE 1/9/87
I herear certify that the information above is true and complet	ie to the best of my knowledge and belief.	·

· , `