

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICA  
(Other instructions on reverse side)

Budget Bureau No. 1004-0135  
Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO.

NM-02127-A

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Federal "C"

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Lynch (Yates-7 Rivers)

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

35, T-20-S, R-34-E

12. COUNTY OR PARISH

Lea

13. STATE  
New Mexico

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER

2. NAME OF OPERATOR

Arlen L. Edgar

915-683-5303

3. ADDRESS OF OPERATOR

208 HBF Bldg, Midland, Texas 79701

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.  
See also space 17 below.)  
At surface

NE/4 NW/4 Section 35

660 FNL + 1980 FWL

T-20-S, R-34-E

Lea County, New Mexico

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON\*

CHANGE PLANS

(Other) Test integrity of downhole

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT\*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

PROCEDURE FOR INTEGRITY TEST

1. Check wellhead for pressure and/or leaks.
2. Nipple down 4 1/2" swedge and pump water until hole is full.
3. Nipple up 4 1/2" swedge and 2000 pound valve - hook up water pumper and pressure up to 250 psi - hold - for 15 minutes - pressure up to 500 psi and hold for 15 minutes - pressure up to 750 psi and hold for 15 minutes - pressure up to 1,000 psi and hold for 15 minutes.
4. Pressure hold - release pressure and close two inch 2,000 pound valve - shut down operations.
5. Well in T A status - casing integrity proven.
6. To be conducted following receipt of approval.

18. I hereby certify that the foregoing is true and correct

SIGNED Arden L. Edgar TITLE Owner

DATE 12-20-85

(This space for Federal or State office use)

APPROVED BY David Adams TITLE Acty

CONDITIONS OF APPROVAL, IF ANY:

DATE 12-23-85

\*See Instructions on Reverse Side

RECEIVED

DEC 26 1985

O.C.D.  
HOMES OFFICE