

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. E-9122

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Southland Royalty Company	8. Farm or Lease Name State AB
3. Address of Operator 1100 Wall Towers West, Midland, Texas 79701	9. Well No. 1
4. Location of Well UNIT LETTER C 660 FEET FROM THE north LINE AND 1980 FEET FROM THE west LINE, SECTION 3 TOWNSHIP 19S RANGE 37E NMPM.	10. Field and Pool, or Wildcat Eumont
15. Elevation (Show whether DF, RT, GR, etc.) 3689' DF	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Rig up. Pull rods & tubing.
2. Run CIBP & set @ 3000'. Cap with 35' cmt.
3. Cut 5½" csg. @ 2650' (TOC @ 2790' by T.S.). Pull 5½".
4. Spot 100' plug across casing stub.
5. Spot 100' plug across 8 5/8" casing shoe @ 1680'.
6. Spot 25' plug at surface.
7. Clean up location, install dry hole marker.

RECEIVED NOV 16 1980
DISTRICT ENGINEER
NEW MEXICO OIL CONSERVATION COMMISSION
FOR THE C-103

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>C. Harney Can</u>	TITLE <u>District Engineer</u>	DATE <u>1-21-80</u>
APPROVED BY <u>Jerry Sexton</u>	TITLE <u>District Engineer</u>	DATE <u>1-21-80</u>
CONDITIONS OF APPROVAL, IF ANY:		