NO. OF COPIES RECEIVED		
DISTRIBUTION		Form C-103
SANTAFE		Supersedes Old C-102 and C-103
FILE	NEW MEXICO OIL CONSERVATION COMMISSION	Effective 1-1-65
U.S.G.S.		
LAND OFFICE		5a. Indicate Type of Lease
OPERATOR	-	State Y Fee
		5. State Oll & Gas Lease No.
(DO NOT USE THIS FORM FOR USE THIS FORM FOR USE TAPPLI	DRY NOTICES AND REPORTS ON WELLS proposals to drill or to deepen or plug back to a different reservoir. cation for permit - " (form C-101) for such proposals.)	
OIL GAS WELL	0THER-	7. Unit Agreement Name
2. Name of Operator		
Gulf Oil Corporation		8, Farm or Lease Name
3. Address of Operator		Lea AP State
Box 670. Hobbs New M	avia, 992/0	9. Well No.
Box 670. Hobbs. New M 4. Location of Well		11
UNIT LETTER I	10. Field and Pool, or Wildcat	
	2090 FEET FROM THE South LINE AND 760	Undesignat ed
THE East LINE, SEC	TION 30 TOWNSHIP 19-S RANGE 35-E NMPM.	
		ΔΗΗΗΗΗΗΗΗΗΗ
	15. Elevation (Show whether DF, RT, GR, etc.)	12. County
16.	3759' GL	Lea
Check	Appropriate Box To Indicate Nature of Notice, Report or Oth	er Data
NOTICE OF	INTENTION TO: SUBSEQUENT	REPORT OF:
		NEI ORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON	COMMENCE DRILLING OPNS.	
PULL OR ALTER CASING	CHANGE PLANS	PLUG AND ABANDONMENT
OTHER Plug back	OTHER	[¬]
7 Deces() B		

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1 103.

10,416' TD, 10,381' PB.

Perforated 5-1/2" casing with 2, 1/2" JHPF at 10,088' to 10,100'. Treated new perfor-ations with 1000 gallons of 15% MC acid, 3000 gallons of 15% NE acid, 6000 gallons of gel water with 1% KCL and 6000 gallons of 20% CR acid. Flushed with 6000 gallons of gel water. Maximum pressure 4800#, minimum 4600#, ISIP 3100#, after 15 minutes 3050#. AIR 5 bpm. Swabbed and tested. No indication of commercial production.

Plans have now been made to plug back as follows: Set CI BP at 10,060' and cap with 5 sacks of cement. Spot 25 barrels of abandonment mud on bottom. Cut and recover 5-1/2" casing from approximately 9050'. Spot 100' cement plug across 5-1/2" casing stub. Spot 156 barr-els of mud on plug. Spot 100' cement plug from 8150' to 8050', across top of Bone Springs formation. Run 5-1/2" casing and set at approximately 6500'. Cement casing with 600 sacks of Class C cement with .5% CFR-2. WOC 24 hours. Test casing with 1000#. Perforate 5-1/2" casing at approximately 6225' to 6420'. Swab and test.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED C. F. Halteredy	R.10,	Area Engineer	DATE March 27, 1972
APPROVED BY CONDITIONS OF APPROVAL, IF ANY:	Orig. Signed by Joe D. Ramey Dist. I, Supv.	TITLE	MAR 27 1972

## RECEIVED

MAR 21 KM