

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
B-9131-1	

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator	No. Wilson Deep Unit
3. Address of Operator	8. Firm or Lease Name
P. O. Box 2055, Roswell, N. M. 88201	Tanza St.
4. Location of Well	9. Well No.
UNIT LETTER <u>L</u> <u>1650</u> FEET FROM THE <u>South</u> LINE AND <u>660</u> FEET FROM	10. Field and Pool, or Well Unit
THE <u>West</u> LINE, SECTION <u>32</u> TOWNSHIP <u>20-S</u> RANGE <u>36-E</u> NMPM.	Undesignated
15. Elevation (Show whether DF, RT, GR, etc.)	12. County
3651 K.B.	Lea

16.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

T.D. 12,644'

3-20-73

Put well on pump. Pump 106 bbls oil 86 bbls. load wtr.

3-22-73

Pumped 16 bbls oil to 46 wtr.

Prep to plug well with plugs as follows:

100' Plug across perf. 12,530' - 12,630'

100' 8400' - 8500' (plan to pull approx 8500' 7" csg.)

100' 6500' - 6400'

100' 5200' - 5100'

100' 3100' - 3000' (plan to pull approx. 3000' 9-5/8" csg.)

100' Top Salt

100' 200' - 300'

10 sx. Top

24 hr. no fee

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED K. J. Ramey TITLE Supt. DATE 7/27/73

Original Signed by
Joe D. Ramey
Dist. L. Supt.

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: