

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
310 Old Santa Fe Trail, Room 206
Santa Fe, New Mexico 87503

WELL API NO. 30-025-24614
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. B-10233
7. Lease Name or Unit Agreement Name State KN 12
8. Well No. 2
9. Pool name or Wildcat Eumont Yates 7 Rivers Queen
10. Elevation (Show whether DF, RKB, RT, GR, etc.)

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	
2. Name of Operator Conoco, Inc.	
3. Address of Operator 10 Desta Drive, Suite 100W, Midland, Texas 79705	
4. Well Location Unit Letter N : 660 Feet From The South Line and 1980 Feet From The West Line Section 12 Township 19-S Range 36-E NMPM Lea County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

10-09-95 RIH and set CIBP @ 3650'.

10-11-95: RIH open ended tubing to 3640'. Displaced hole w/salt gel mud and spotted 100' cement on CIBP. Pulled up to 1025'. Spotted cement to 550'. POOH. RIH w/retainer. Set Retainer @ 450'. Squeeze leak w/100 sx. POOH.

10-17-95: Perforate and squeeze holes @ 360'. Establish circulation behind 4-1/2" to surface. Circulate cement. Cut off wellhead and installed marker.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Ann E. Ritchie TITLE Regulatory Agent DATE 12-17-95

TYPE OR PRINT NAME Ann E. Ritchie (915) TELEPHONE NO. 684-6381 / 686-5424

(This space for State Use)

APPROVED BY Johnny Robinson TITLE Regulatory Agent DATE 12-17-95

CONDITIONS OF APPROVAL, IF ANY: