Form	# 31L
(May	1963

14. PERMIT NO.

REPAIR WELL

(Other)

	144 Q. C. C
DEPARTMEN. OF THE INTERIOR Verse wide) GEOLOGICAL SURVEY	Form approved. Budget Bureau No. 42 R1424, 5. MEASE DESIGNATION AND SERIAL NO. NM-9030
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
OIL GAS OTHER	7. UNIT AGREEMENT NAME
NAME OF OPERATOR	8. FARM OR LEASE NAME
NRM PETROLEUM CORPORATION ADDRESS OF OPERATOR	Federal "22" 9. WELL NO.
900 Building of the Southwest, Midland, Texas 79701	1
LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.)	10. FIELD AND POOL, OR WILDCAT

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

3651 DF


NOTICE OF INTENTION TO: TEST WATER SHUT-OFF PULL OR ALTER CASING FRACTURE TREAT MULTIPLE COMPLETE SHOOT OR ACIDIZE ABANDON* CHANGE PLANS

660' FWL & 990' FNL Section 22

WATER SHUT-OFF REPAIRING WELL FRACTURE TREATMENT ALTERING CASING SHOOTING OR ACIDIZING ABANDONMENT* (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and sones pertinent to this work.) *

Set Cast Iron Bridge Plug at 3500'; Spotted 50 sx. Halliburton cement 3100-2300'; Pulled tubing to 2300'; reverse one (1) barrel cement; spotted 50 sx. 2300-1200'; Pulled out of hole; Cement was Trinity Lite Wate with 13# salt per sx; 5/10% HR-7. Set 20' cement in top of well and capped with permanent marker.



TITLE	Vice-President	
TITLE	2.7476750	DATE
		्र अध्यक्षका र स्ट

*See Instructions on Reverse Side