

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department
OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

Form C-103
Revised 1-1-89

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Drawer Dd, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, Nm 87410

API NO. (assigned by OCD on New Wells) 30-025-25395	
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>	
6. State Oil & Gas Lease No. N/A	
7. Lease Name or Unit Agreement Name NORTH MONUMENT ABO UNIT	
8. Well No. 1	
9. Pool name or Wildcat NORTH MONUMENT ABO POOL	
10. Elevation(Show whether DF, RKB, RT, GR, etc.) 3741'	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)



1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	
2. Name of Operator CHEVRON U.S.A. INC.	
3. Address of Operator P.O. BOX 1150 MIDLAND, TX 79702 ATTN: NITA RICE	
4. Well Location Unit Letter G : 1650 Feet From The NORTH Line and 1700 Feet From The EAST Line Section 14 Township 19S Range 36E NMPM LEA County	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CMT JOB <input type="checkbox"/>
OTHER: ADD PAY & ACID FRAC <input checked="" type="checkbox"/>	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations(Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

WE PROPOSE TO: MIRU ND WH, NU BOP. POH W/TBG. SET CIBP @7400' DUMP 20' CMT ON TOP. PERF 7214'-7272'. ACID FRAC W/12,000 GALS OF GELLED 15% HCL. PERF F/7052'-7124'. ACID FRAC W/20,000 GALS OF GELLED 15% HCL. PERF F/6946'-6982'. ACID FRAC W/10,000 GALS GELLED 15% HCL. RIH W/TBG. ND BOP, NU WH. TURN WELL OVER TO PRODUCTION.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE 	TITLE TECH. ASSISTANT	DATE 8/1/94
TYPE OR PRINT NAME WENDI KINGSTON	TELEPHONE NO. (915)687-7436	
APPROVED BY 	TITLE DISTRICT I SUPERVISOR	DATE AUG 03 1994

CONDITIONS OF APPROVAL, IF ANY: