Submit 3 Copies To Appropriate District State of New Me	
<u>District I</u> Energy, Minerals and Natur	WELLADING
1625 N. French Dr., Hobbs, NM 88240 District II 1301 W. Grand Avenue Artesia, NM 88210 OIL CONSERVATION	70-005-7/207
District III 1220 South St. Fra:	ncis Dr. 5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410 District IV Santa Fe, NM 87	TATE I FEE I
1220 S. St. Francis Dr., Santa Fe, NM 87505	o. State on & Gas L sase No.
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLU DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FO PROPOSALS.)	
1. Type of Well: Oil Well Gas Well Other Bring [Vel]	
2. Name of Operator	8. Well No.
3. Address of Operator	9. Pool name or Wildcat
PC Box 513 Hobbs Nm 88241	
4. Well Location	
Unit Letter J: 1980 feet from the Soft line and 1980 feet from the East line	
Section 5 Township 195 Ra	nge 36 E NMPM County Lea
10. Elevation (Show whether DR, RKB, RT, GR, etc.)	
11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO: SUBSEQUENT_REPORT OF:	
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALT ERING CASING	
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT	
PULL OR ALTER CASING MULTIPLE CASING TEST AND CEMENT JOB	
OTHER:	OTHER:
12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.	
	101112
See Attached	
See All	
5 ee #172 15 15 15 15 15 15 15 15 15 15 15 15 15	
I hereby certify that the information above is true and complete to the best of my knowledge and belief.	
SIGNATURE Walto Brun TITLE	Asst Manager DATE 11-26-02
Type or print name /// /fer Brisco Telephone No. 505-393-8352	
(This space for State use)	
APPPROVED BY ORIGINAL SIGNED BY DATEEC 0 9 26.02	
Conditions of approval, if any: GARY W. WINK OC FILLD REPRESENTATIVE II/STAFF MANAGER	

了 こ ら 11-23-02- Rig up, Run in the hole with sinker bar on sand line. Tubing plugged @ 1200 ft. Tried to unplug tubing. Pulled sinker bar and sandline out of tubing and shut down.

11-24-02- Off

11-25-02- Get pit lined

11-26-02- Tripped out of the hole with tubing. Plugged (a) 1200 ft. Laid 5 joints of plugged 2 7/8 tubing. Finished tripping out of the hole. Trip back in hole, picked up 5 joints 2 7/8 tubing. Flange up well, Job complete.

