Form 3160-5 (June 1990)

Subsequent Report

Final Abandonment Notice

## **U...TED STATES** DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

Non-Routine Fracturing

Conversion to Injection

Water Shut-Off

Dispose Water

N.M. OIL CONS. MEXICO 88240

FORM	V V C C C C C C C C C C C C C C C C C C	Thirties.
BARS	eau No. 10	04-0135
Expires:	March 31,	1993

	Expires:	March	31,	1993
5.	Lease Designati	on and	Serial	No.
MM	052424			

SUNDRY NOTICES AND REPORTS ON WELLS  Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.		6. If Indian, Allottee or Tribe Name	
SUBMIT IN TRIPLICATE		7. If Unit or CA, Agreement Designation Lea Unit	
Type of Well		8. Weil Name and No.	
Name of Operator		Lea Unit 12	
Marathon Oil Company		9. API Well No.	
. Address and Telephone No.		130-025-26365	
P.O. Box 552, Midland, TX 79702 915-682-1626		10. Field and Pool, or exploratory Area	
Location of Well (Footage, Sec., T., R., M., or Survey Description	on)	Lea (Bone Spring)	
UL "H". 1980' FNL & 990' FEL Sec 13, T-20-S, R-34-E		11. County or Parish, State	
		Lea NM	
CHECK APPROPRIATE BOX(s) TO	NO INDICATE NATURE OF NOTICE, REPO	ORT, OR OTHER DATA	
TYPE OF SUBMISSION	TYPE OF ACTION		
Notice of Intent	Abandonment	Change of Plans	
	X   Recompletion	New Construction	

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) 13 Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

Other

Plugging Back

Casing Repair

Altering Casing

Marathon Oil company intends to add pay and stimulate this well as per the summarized procedure below.

MIRU PU. POOH with rods and pump. NU BOP. POOH with tubing. Test BOP blind and pipe rams. Perforate the 3rd Bone Spring W/2 JSPF 10.970-84, 10-989-11.113. 11.036-11.046. Set treating Packer @ 10,900'. Stimulate with 2500 gallons 15% HCL. If BHP and swab tests acceptable frac well as per service company recommendation. POOH with treating string. Clean out to frac sand as necessary. Install 2 7/8" production tubing. SN @ 11.165 +-. ND BOP. NU wellhead. Install 1 1/4" rod pump and rods. Hang well off and turn to test.

14. I hereby certify that the foregoing is true and correct Signed	Title A	dvanced Eng. Tech.	Date 8/21/95	
(This space for F(ORIG. SCD.) (ORIG. LARA Approved by Conditions of approval, if any:	Title _	PETROLEUM ENGINELLI.	Date <u>9/22/9</u>	5

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction