

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.O.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-101
Revised 10-1-78

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. 18634	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO CELEPHEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input type="checkbox"/> OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-		7. Unit Agreement Name
2. Name of Operator Gulf Oil Corporation		8. Farm or Lease Name Graham State (NCT-C)
3. Address of Operator P. O. Box 670, Hobbs, NM 88240		9. Well No. 10
4. Location of Well UNIT LETTER <u>B</u> <u>990</u> FEET FROM THE <u>North</u> LINE AND <u>1980</u> FEET FROM THE <u>East</u> LINE, SECTION <u>24</u> TOWNSHIP <u>19S</u> RANGE <u>36E</u> N.M.P.M.		10. Field and Pool, or Wildcat Eumont Gas
15. Elevation (Show whether DF, RT, GR, etc.) 3601' GL		12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input checked="" type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TD 7-7/8" hole 7-24-80. RU & ran 93 joints & 1 cut joing 5½" 14# K-55 ST&C (3739') set at 3750', float collar at 3715'. Cement with 600 sacks "C" with 16% gel Gulfmix & 300 sacks "C" neat. Plug down at 3:45 A.M., 7-25-80. Circulate cement. WOC 18 hours. Drill float collar & cement.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>J. L. Sexton</u>	TITLE <u>Area Drilling Supt.</u>	DATE <u>8-15-80</u>
APPROVED BY <u>Jerry Sexton</u>	TITLE <u></u>	DATE <u>8-15-80</u>
CONDITIONS OF APPROVAL, IF ANY:		