

NEW MEXICO OIL CONSERVATION COMMISSION

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

5a. Indicate Type of Lease
State ☒ Fee ☐
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR NOTICES TO ABANDON OR TO REPERFORATE WELL BACK TO A DIFFERENT RESERVOIR.
SEE APPLICATION FOR REPERFORATION (FORM C-101) FOR SUCH PROCEEDINGS.)

1. ☒ OIL WELL ☐ GAS WELL ☐ OTHER	7. Unit Agreement Name
2. Name of Operator Hamon Operating Company	8. Name of Lease (Name) Hamon, Samuel Petty
3. Address of Operator P. O. Box 5025 Midland, TX 79704-5025	9. Well No. 1
4. Location of Well UNIT LETTER <u>N</u> <u>660</u> FEET FROM THE <u>South</u> LINE AND <u>1980</u> FEET FROM THE <u>West</u> LINE, SECTION <u>8</u> TOWNSHIP <u>20S</u> RANGE <u>36E</u> N.M.P.M.	10. Field and Pool, or Wildcat N. Claude Bone Spr
15. Elevation (Show whether DF, RT, CR, etc.)	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☒	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOBS ☐	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Set C.I.B.P. above perforation. Perforate @ 8604' w/35 Ft. of cement on top or 100' cement plug @ perforation and tag.
2. Load hole with mud.
3. Cut 7" casing @ free point @ approximately 6000' plus and set 100' plug; 50'in and 50'out of stub and tag.
4. Set 100' cement plug @ 9 5/8 shoe. 50' in and 50' out and tag.
5. Set 100' cement plug @ base of salt - 3100'.
6. Set 100' cement plug @ top of salt - 1600'.
7. Set 10 sacks of cement @ top hole plug.
8. Install P & A marker.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Raymond O. McDonald TITLE P & A Supervisor DATE 8-26-86

Orig. Signed by
Paul Kautz
Geologist

APPROVED BY _____ TITLE _____ DATE AUG 27 1986

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED
AUG 26 1986
O.C.S.
HOBBS OFFICE