

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease
State ☐ For ☒

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	7. Unit Agreement Name
2. Name of Operator Hamon Operating Company	8. Farm or Lease Name Hamon Samedan Petty
3. Address of Operator P.O. Box 5025, Midland, Tx. 79704-5025	9. Well No. 1
4. Location of Well UNIT LETTER <u>N</u> , <u>660</u> FEET FROM THE <u>South</u> LINE AND <u>1980</u> FEET FROM THE <u>West</u> LINE, SECTION <u>8</u> , TOWNSHIP <u>20-S</u> , RANGE <u>36-E</u> , N.M.P.M.	10. Field and Pool, or Wildcat Osuda N. Bone Spring
15. Elevation (Show whether DF, RT, GR, etc.) 3622.2' GR - 3646' KB	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <u>Plug back & Perforate</u> <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Set CIBP @ 8805' KB
2. Bailer dumped 3 sy, cmt, on T/CIBP from 8805' - 8797'
3. Perforated Bone Spring @ 8604' - 10'
4. Swab Tested well, making 100% water

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED B.W. Cozart (B.W. Cozart) TITLE Dist. Oper. Supt. DATE 7-22-86

ORIGINAL SIGNED BY JERRY SEXTON
PROVED BY DISTRICT 1 SUPERVISOR TITLE DATE 8-1-1986

CONDITIONS OF APPROVAL, IF ANY: