Submit 3 Copies to Appropriate

CONDITIONS OF APPROVAL, IF ANY:

## State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103

District Office	Energy, winicials and Natural I	Resources Department		Revised 1	l-1-89
DISTRICT I	x 1980, Hobbs NM 88241-1980 2040 Pacheco St.				
P.O. Box 1980, Hobbs NM 88241-1980			WELL API NO. 30-025-26821		
DISTRICT II P.O. Drawer DD, Artesia, NM 88210	Santa Fe, NM 87505		5. Indicate Typ		
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410				STATE .	FEE 🗆
			6. State Oil & C	ras Lease No.	
SUNDRY NOTICES AND REPORTS ON WELLS  (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A					
DIFFERENT RESERVOIR. USE "APPLICATION FOR PENMIT"  (FORM C-101) FOR SUCH PROPOSALS.)			7. Lease Name or Unit Agreement Name		
1. Type of Well: OIL GAS WELL WELL X	OTHER	L. W.WHITE (NCT-A) COM			
2. Name of Operator	OTHER		0 77 77		
Chevron U.S.A. Inc.			8. Well No. 7		
3. Address of Operator P.O. Box 1150, Midland, TX	79702		9. Pool name or	Wildcat S-7 RVRS-QUEEN (F	——————————————————————————————————————
4. Well Location	MODELL			S 7 KVKS QUEEN (F	-KU GAS)
Unit Letter A : 990	Feet From TheNORTH	Line and660	Feet Fro	om The EAST	Line
Section 25	Township 20S Ra	.nge 36E 1	NMPM	LEA	C
	10. Elevation (Show whether	er DF, RKB, RT, GR, etc.	)		County
11. Check Ani	propriate Roy to Indicate	Natura of Nation	Domont	<u> </u>	
The Control of the Indicate Nature of Notice, Report, or Other Data					
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:					
PERFORM REMEDIAL WORK	PLUG AND ABANDON X	REMEDIAL WORK		ALTERING CASING	
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING			OPNS.	PLUG AND ABANDON	ILAENIT
PULL OR ALTER CASING		CASING TEST AND CEM		I EGG AND ADAMON	WENT -
OTUED.			LINI JOB		۲-
		OTHER:			
<ol> <li>Describe Proposed or Completed Opera work) SEE RULE 1103.</li> </ol>	itions (Clearly state all pertinent deta	ils, and give pertinent date	s, including estim	ated date of starting any	proposed
TAG CIBP @ 3640'. SET BA	LANCED PLUG 3640'-3540'.	SET BALANCED PLUG :	3468'-3368'.		
SET BALANCED PLUG 3325'-3225'. SET BALANCED PLUG 2902'-2802'. SET BALANCED PLUG 2638'-2538'. SET BALANCED PLUG 1050'-950'. SET BALANCED PLUG 411'-311'. SET					
BALANCED PLUG 100' - SURF. CUT OFF WH & SET P&A MARKER.					
I hereby certify that the information above is true	and complete to the best of my knowledge ?	and belief.			
SIGNATURE	10.	TECHNICAL ASSISTA	NT.	2 (20 (	100
7	TITLE	TEGINITUAL MOSISTA	17 (	DATE3/29/	33
TYPE OR PRINT NAME J. K. RIPLEY	<u>V</u>			ELEPHONE NO. (915)68	<u>37-7148</u>
(This space for State Use)					
ORICINAL SIGN	ITO BY COLLAR WELLBAMS THE THE SAME OFF			Arman, A	
APPROVED BY DIGITIES	TITLE			DATE	

\_\_ DATE \_\_