

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-79

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease
State ☐ Fee ☒
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL ☐ GAS WELL ☒ OTHER ☐	7. Unit Agreement Name
Name of Operator <i>Hamon Operating Company</i>	8. Farm or Lease Name <i>Childers</i>
Address of Operator <i>First Republic Bank Center, 3900 Tower 1, Dallas, Texas 75201-3902</i>	9. Well No. <i>1</i>
Location of Well UNIT LETTER <i>K</i> <i>1980</i> FEET FROM THE <i>West</i> LINE AND <i>1650</i> FEET FROM THE <i>South</i> LINE, SECTION <i>32</i> TOWNSHIP <i>19-S</i> RANGE <i>36-E</i> NMPM.	10. Field and Pool, or Wildcat <i>Wildcat</i>
15. Elevation (Show whether DF, RT, GR, etc.) <i>3642.1' GR 3666' KB</i>	12. County <i>Lea</i>

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
ULL OR ALTER CASING ☐
OTHER ☐

PLUG AND ABANDON ☒
CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOBS ☐
OTHER ☐

ALTERING CASING ☐
PLUG AND ABANDONMENT ☐

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

PBTD is 11,780'. Operator proposes to P: A as follows:

1. Set CIBP @ 10,736' (T/Atok) w/ 35' cmt. above BP.
2. Set 100' cmt. plug @ T/Bone Spring (7430'-7330')
3. Cut & Pull 7" csg. @ free point est. to be @ 7000' ± *PLACE CUT POINT 50' IN 5500'*
4. Set 100' cmt. Plug @ 5600'-5500' (B/9 7/8" csg. is @ 5550')
5. Set 100' cmt. Plug @ T/yates (3255'-3255')
6. Set 100' cmt. Plug @ T/5alt (1877'-1777')
7. Set 100' cmt. plug @ 411'-311' (B/13 7/8" csg. @ 361')
8. Set 10 sx. cmt. plug in top of 9 7/8" csg.
9. Weld dry hole plate on top of csg. 3' below G.L.
(Well is in irrigated field)

THE COMMISSION MUST BE NOTIFIED IN WRITING PRIOR TO THE BEGINNING OF DRILLING OPERATIONS FOR THE WELL TO BE ABANDONED.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

CO *[Signature]* TITLE *Dist. Op. Supt.* DATE *7-22-87*
ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR
TITLED *JUL 27 1987*

DITIONS OF APPROVAL, IF ANY:

RECEIVED
JUL 24 1987
OCCO
HOBBS OFFICE