COPY TO O. C. C.

Form Approved. Budget Bureau No. 42-R1424

UNITE	UNITED		S
DEPARTMENT	OF	THE	INTERIOR
GEOLOGI	CAL	SUR	VEY

	LEASE							
_	244	1730	1-6 C	e = 1	/ 3	9.	2 1	1%
	IF INDIAN						'	•

GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME				
	TO THE ON TRIBE NAME				
SUNDRY NOTICES AND REPORTS ON WELLS	7. UNIT AGREEMENT NAME				
(Do not use this form for proposals to drill or to deepen or plug back to a different	WEST LYNCH DEEP UNIT				
reservoir. Use Form 9-331-C for such proposals.)	8. FARM OR LEASE NAME				
1. oil gas va	ON LEASE NAME				
well well well other	9. WELL NO.				
2. NAME OF OPERATOR	1 3 2 T				
THE SUPERIOR OIL COMPANY	10 5151 0 00 1111				
3. ADDRESS OF OPERATOR	10. FIELD OR WILDCAT NAME				
P. O. BOX 4500 THE WOODLANDS, TEX. 77380	WILDCAT				
	11. SEC., T., R., M., OR BLK. AND SURVEY OR				
 LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.) 	AREA CONTROL				
AT SURFACE: 2310' FEL & 660' FSL of SEC	Sec. 28, T20S, R34E				
AT TOP PROD. INTERVAL:	12. COUNTY OR PARISH 13. STATE				
AT TOTAL DEPTH: Straight Hole	Lea New Mexico				
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE.	14. API NO. 2 # 2 2 2 2 2 2 2				
REPORT, OR OTHER DATA					
THE STATE OF STATE OF THE STATE	15. ELEVATIONS (SHOW DF, KDB, AND WD)				
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	KDB-3752', GL-3728'				
TEST WATER SHUT-OFF					
FRACTURE TREAT	- Barana - B				
SHOOT OR ACIDIZE					
REPAIR WELL	(NOTE: Papert and the				
PULL OR ALTER CASING	(NOTE: Report results of multiple completion or zone change on Form 9-330.)				
MULTIPLE COMPLETE					
CHANGE ZONES	그는 그는 그를 가장하는 것이 뭐를 가셨다. 없는				
(other)					
	그 그 그 그 그 그 그 그 그 그 그 그 그 그 그 그 그 그 그				
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state including estimated date of starting any proposed work. If well is di	all pertinent decite 5-4				
including estimated date of starting any proposed work. If well is di measured and true vertical depths for all markers and zones pertinent	rectionally drilled, give subsurface locations and to this work.)*				
	一				
COMPLETION PROCEDURE:	。				
	2 - 1/1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 -				
 Clean out hole. 	를 보통 - 한 트 한 국국 소선 ♥				
2. Set Packer @ 13,525'					
3. Set Packer @ 13.135'	H. S. GEREOGICAL SURVE				
4. Perforate 5 1/2" casing from 13,725' to	13 7411 W/A ICABOUS NEW MEXICO				
5. Test Well	103141 N/4 OSHOODS 12 (F-				
6. Well on production					
p. 500001011	그 그 그 그 그 얼마를 들는 말을 가고 있다면 하다.				
NOTE: Jim Gillham gave verbal approval to de	John the CDL To 1 (O)				
gate terbar approvat to de	riete the CBL on 5 1/2" casing.				
Subsurface Safety Valve: Manu. and Type	Set @ Ft.				
18. I hereby certify that the foregoing is true and correct					
70/71 7 .	2,02,03				
SIGNED L.H.BOHOTTITLE Engr. Supervis					
(This space for Federal or State office	NCINEER				
APPROVED (Orig. Sgd.) PETER W. CHESTER TITLE DISTRICT E	DATE SEP 1 5 1980				
(C: (O+3) PB, CRC, LH, RG, CF					
-,, 10, 61	<u></u>				